



Conservation Plan for Heritage Resources - 8204 Kipling Avenue, Part of Lot 9, Concession 8, Township of Vaughan, now City of Vaughan, Regional Municipality of York, Ontario

Project number: PHC-2021-026

Report Type: Original

Report Date: 31 October 2022

Proponents: LCT Investment Group Ltd.

Address: 70 Don Park Road – Unit 1, Markham ON L3R 1G4

ATTACHMENT 3
8204 KIPLING

Content

1. Executive Summary	7
2. Personnel	8
3. Introduction	9
3.1 Site Description and Context	9
4. Statement of Significance	10
4.1 Character Defining Elements	10
5. Building Condition	11
5.1 Exterior	11
5.2 Interior	28
6. Conservation Principals	40
6.1 CHP Standards and Guidelines	40
6.2 Qualified Specialists	41
6.3 Moody-Darker House Rehabilitation	41
6.4 Repair or Replacement of Deteriorating Features	42
6.4.1 Masonry Repair	42
6.4.2 Roof Repair	42
6.4.3 Windows and doors	42
6.4.4 Facia and Soffit	42
6.4.5 Millwork	42
6.4.6 Veranda	42
6.5 Alteration or Additions for Continued Use	42
6.6 Depiction During a Particular Period	43
7. Work to be Undertaken	47
7.1.1 Understand and Document Existing Condition	47
7.1.2 Permitting	47
7.1.3 Stabilization	47
7.1.4 Relocation	47
7.1.5 Foundation	47
7.1.6 Masonry Repair	47
7.1.7 Windows and Doors	48
7.1.8 Millwork	48
7.1.9 Veranda	48
7.1.10 Interior	48
8. Intervention Solutions	49
8.1 Moving Plan	49
8.2 Cost Estimate	49
9. Schedule of Work	50
10. Next Steps	51
11. Bibliography and Reference Documents	52

List of Images and Tables

Image 1: Front façade of Moody-Darker House, facing west.....	12
Image 2: Northeast corner of Moody-Darker House, facing southeast.....	13
Image 3: North face of Moody-Darker House, facing south.....	13
Image 4: Northwest corner of Moody-Darker House, facing southeast.....	14
Image 5: West face of Moody-Darker House, facing east, note board and batten addition with upper balcony.....	14
Image 6: South face of Moody-Darker House, facing north.....	15
Image 7: Southeast corner of Moody-Darker House, facing northwest.....	15
Image 8: Only remaining original wood window, four light awning style in basement window well.....	16
Image 9: Bay on south face of structure, note decorative voussoirs and carved key stones.....	17
Image 10: Bay window on front façade of Moody-Darker House.....	18
Image 11: Close up of dichromatic brick voussoir with carved keystone.....	19
Image 12: Close up of voussoirs with decorative cut buff brick finish as used on east and south face of structure....	19
Image 13: Ribbon pointing present in voussoirs.....	20
Image 14: Representative example of dichromatic decorative quoining with ribbon pointed mortar.....	20
Image 15: Representative example of dichromatic decorative element on second storey.....	21
Image 16: Closeup of decorative diamond pattern typical of gables.....	21
Image 17: Closeup of brick panels located below structural openings on bays, note extensive water damage to brick and mortar.....	22
Image 18: Closeup of remaining ribbon pointing in brick façade.....	22
Image 19: Use of modern aluminum fascia, soffit and eavestrough.....	23
Image 20: Example of field stone foundation with flush bond mortar.....	23
Image 21: Rear of structure showing signs of removal of previous rear addition.....	24
Image 22: Aluminum fascia used to cover suspected attachment point of drop pendant decoration.....	24
Image 23: Large air vent located in gable end of front façade, note remains of original diamond dichromatic brickwork below grate.....	25
Image 24: Hip roof dormer on south side of Moody-Darker House.....	25
Image 25: Modification to north dormer of structure, sill is cast concrete and brick work does not match with rest of home.....	26
Image 26: Example of cracking in brick veneer.....	26
Image 27: Large window on north face of structure, sill has been replaced with cast concrete and voussoir shows signs of deformation.....	27
Image 28: Example of typical brick exfoliation resulting from poor water management.....	27
Image 29: Interior of bay on front of home.....	28
Image 30: Extant stairs, note deformation of trim around door resulting from water infiltration.....	29
Image 31: Typical example of the interior of structure, facing north.....	29
Image 32: Example of modern ceiling and use of recessed lighting.....	30
Image 33: Evidence of past renovation, note use of sistered joists.....	30
Image 34: Rear hall on first floor, note mould growth and floor damage indicative of extensive water damage, facing west.....	31
Image 35: Kitchen on first floor, facing southwest.....	32
Image 36: Area where large section of wall has been removed, facing southwest.....	32

Image 37: Steel I-beam used to replace structure where wall has been removed..... 33

Image 38: Landing on second floor at top of stairs..... 33

Image 39: Front room of second floor located in gable end of structure, facing east 34

Image 40: Modern roof construction on second floor 34

Image 41: Rear room on second floor, facing north, windows are located in hip dormer depicted in Image 25, note water damage to flooring 35

Image 42: Water damage typical of that observed on second floor..... 35

Image 43: Example of new roof framing..... 36

Image 44: Example of new wall framing with original brick behind 36

Image 45: Stairs to basement..... 37

Image 46: Example of original framing with horizontal board sheathing augmented by modern 2x4 framing..... 37

Image 47: Basement, facing southwest..... 38

Image 48: Typical example of water damage and mould growth in basement 38

Image 49: Overview of basement 39

Image 50: I-joists used to replace original floor joists, typical of entire first floor as seen from basement..... 39

Image 51: c.1971 image of Moody-Darker House, note original windows and doors..... 43

Image 52: c.2000 image detailing original front door and sidelights..... 43

Image 53: Original moulded soffit and fascia, date of photo unknown 44

Image 54: Example of the type of gable detail that may have been present on Moody-Darker House..... 44

Image 55: Example of window style that should be used in Moody-Darker House..... 45

Image 56: Example of temporally appropriate veranda design, gable decoration is also evident in the image 46

Table 1: Task Importance and Resource Cost Estimate 50

Appendices

- Appendix A: Qualifications
- Appendix B: Proposed Development Plan
- Appendix C: Moody-Darker House Floor Plan
- Appendix D: Contact Sheet of All Available Photos
- Appendix E: Existing Elevations
- Appendix F: Conservation Elevations

1. Executive Summary

Parslow Heritage Consultancy, Inc. (PHC) was retained by LCT Investment Group Ltd. (the Proponent) to prepare a Conservation Plan for Heritage Resources (CPHR) for the property containing the Moody-Darker House, located at 8204 Kipling Avenue, Woodbridge, a suburb of the City of Vaughan, Regional Municipality of York, Ontario. The Proponent is applying for a building permit to the City of Vaughan in order to undertake alterations to the property located on part of Lot 9, Concession 8, Geographic Township of Vaughan, now City of Vaughan. The extant structure located at 8204 Kipling Avenue has been identified as a contributing structure to the North Kipling Avenue portion of the larger Woodbridge Heritage Conservation District.

When 8204 Kipling Avenue is evaluated against the criteria presented in Ontario Regulation 09/06 (Section 7.3), the property is found to meet the criteria set forth to identify Cultural Heritage Value or Interest (CHVI), and in doing so agrees with the previous findings of the *Woodbridge Heritage Conservation District Study and Plan* (City of Vaughan 2009).

The Cultural Heritage Impact Assessment (CHIA) for the property found that relocation and rehabilitation of the structure is the preferred method of mitigation for this Project (PHC 2021). Relocation of the structure will allow for the extension of Meeting House Road, the development of the surrounding lands and the retention of the heritage resource. Given the CHVI of 8204 Kipling Avenue, preventative measures must be taken to ensure the extant structure is not compromised during the relocation process.

The purpose of this CPHR is to describe in detail the proposed work to the heritage resource in an effort to ensure its longevity. This CPHR serves as a complementary document to the CHIA already prepared for the property (PHC 2021).

This CPHR has been prepared at the request of the City of Vaughan Planning Department and is designed to meet the scope of work stipulated in the City of Vaughan's *Guidelines for Preparing a Conservation Plan for Heritage Resources* (City of Vaughan 2019b).

A site visit was conducted on March 25, 2021 to document the structure.

2. Personnel

Carla Parslow, Ph.D., CAHP	Senior Cultural Resource Specialist
Christopher Lemon, B.Sc., Dip. Heritage	Lead Cultural Heritage Specialist
Adam Long, M.Sc.	Cultural Heritage Assistant
Jamie Lemon, M.A.	Project Manager

Acknowledgements

Gary Tsang	Property Owner
Joanna Fast	Evans Planning Inc.
Carrie Logtenberg	Archival Record Analyst, City of Vaughan

3. Introduction

Parslow Heritage Consultancy, Inc. (PHC) was retained by LCT Investments Ltd. (the Proponent) to prepare a Conservation Plan for Heritage Resources (CPHR) for the property at 8204 Kipling Avenue, Woodbridge, a suburb of the City of Vaughan, Regional Municipality of York, Ontario. The Proponent is undertaking this work as part of the application process to the City of Vaughan to undertake re-development of the property located on part of Lots 8 and 9, Concession 8, Geographic Township of Vaughan, now City of Vaughan. The extant structure located at 8204 Kipling Avenue is located on part of Lot 9 Concession 8 and has been identified as a contributing structure to the North Kipling Avenue portion of the larger Woodbridge Heritage Conservation District (HCD). The extant structure located at 8204 Kipling Avenue is known locally as the Moody-Darker House (Subject Property).

This CPHR has been prepared at the request of the City of Vaughan Planning Department and is designed to meet the scope of work stipulated in the City of Vaughan's *Guidelines for Preparing a Conservation Plan for Heritage Resources* (City of Vaughan, 2019b).

The purpose of this CPHR is to describe in detail the proposed work to the heritage resource in an effort to ensure its longevity and serves as a complementary document to the Cultural Heritage Impact Assessment (CHIA) previously prepared for the property (PHC 2021).

A site visit was conducted on March 25, 2021 to document the structure.

Applicant Information:

The proposed development application is being made by the investment group that owns the property, through their representative Gary Tsang.

LCT Investment Group Ltd.
70 Don Park Road – Unit 1
Markham, Ontario, L35 1G4

3.1 Site Description and Context

The Subject Property is situated on Part of Lot 9, Concession 8 in the former Township of Vaughan, now city of Vaughan, Regional Municipality of York. The property is situated on the east side of Kipling Avenue and contains the structure identified as 8204 Kipling Avenue, Vaughan, Ontario. The Subject Property was part of the historic Village of Woodbridge that existed until 1971, at which time it was subsumed into the City of Vaughan (City of Vaughan nd). The property is currently located within the Woodbridge HCD) in the Kipling Avenue North subregion (City of Vaughan 2009).

The Subject Property is approximately 3.24 acres in size and contains a single storey-and-a-half residential structure constructed in the Gothic Revival architectural style, which was popular in Canada between 1830 and 1900 (Blumenson 1989). The property is confined by the Canadian Pacific Railway corridor to the west, an unnamed street to the north and Kipling Avenue to the east. The property at 8024 Kipling Avenue is currently unoccupied and has been subject to extensive modification to the interior finishes.

4. Statement of Significance

The Moody-Darker House is situated on Part of Lot 9, Concession 8 in the former township of Vaughan, now city of Vaughan, Regional Municipality of York. The structure is situated on the west side of Kipling Avenue at the intersection of Meeting House Road and Kipling Avenue. The structure is the only remaining element of the former Moody Family farmstead. The Moody-Darker House is a storey-and-a-half residential structure constructed in the Gothic Revival architecture style. The structure has been previously identified as a contributing structure to the North Kipling Avenue subsection of the Woodbridge HCD. The Moody-Darker House serves as a representative example of the Gothic Revival architectural style popular in the late 19th and early 20th century. The dichromatic brick, decorative voussoirs with keystones and use of tuck-pointed mortar display a high degree of craftsmanship and artistic merit. The residence is important in defining, maintaining, and supporting the historic character of the area. The Moody-Darker House serves as a reminder of the agricultural heritage of Woodbridge and aids in delineating the historic boundaries of the early community. The structure is one of several stylistically similar residences in the area and is important to defining and maintaining the historic style and character of the area.

4.1 Character Defining Elements

- Massing of storey-and-a-half residential structure
- Dichromatic brick
- Tuck-pointed masonry
- “V” shaped quoins on all corners
- Elaborate voussoirs with key stones
- Brick panels below bay windows
- Medium pitched gable roof
- Cross gable roofline
- Original single stack chimneys
- Bay windows with lower panels
- Wrapping veranda

5. Building Condition

5.1 Exterior

The structure at 8204 Kipling Avenue is a storey-and-a-half frame structure with red brick veneer, augmented with buff brick details. The structure presents with a “T” plan with short-faced façade. The structure has a medium pitched gable roof with cross gable. The structure has a maximum length of 15 m measured east to west, and a maximum width of 9 m measured north to south. The main façade faces east and presents a three-bay design. The front façade includes an open veranda of contemporary construction and a one-storey bay window; a second one-storey bay window is located on the south face.

The structure is indicative of rural Ontario architecture of the late 19th and early 20th century, with the “T” shaped plan with cross gable being a temporally common design across southern Ontario during what is commonly referred to as the Gothic Revival Period, ca. 1830-1900 (Blumenson 1989). This example displays characteristics of a subset of Gothic Revival architecture known as Victorian Gothic; this vernacular adaptation of the style is also prominent throughout the surrounding area. The basic design of the home with its gable roof lines and medium pitched central gables is indicative of the Gothic Revival style, while the inclusion of the bay window, use of round headed windows, and plentiful dichromatic brickwork are all in keeping with the Victorian Gothic subset of the of architectural style.

The exterior of the home is clad in red brick laid in stretcher bond, augmented using buff brick. Buff brick has been incorporated into the triangular quoins at all corners, voussoirs above all structural openings, a decorative pattern on the upper storey and inset panels below the windows on the bay of the front façade and south side. The structural openings on the east and south sides of the structure contain keystones constructed of cut stone. The home is pointed in brick red mortar and evidence of the original white tuck pointing is visible in many areas. The structure has been constructed on a coursed field stone foundation.

The rear wall of the structure deviates from the rest of the home in that it is constructed of a lower quality brick and does not utilize the buff brick details present on the remainder of the home. Evidence in the form of a ghost outline is present on the rear of the home, indicating the removal of a previous addition.

The main entrance is offset to the south side of the front façade and displays a segmentally headed transom. The front door and transom have been replaced, as have all windows. The front façade of the home is slightly off center resulting in the roofline truncating the hood associated with the southern window on the second floor. All exterior woodwork, fascia, soffit and structural opening details have been clad in modern aluminum. The front gable exhibits a modern louvered vent that has replaced the original buff brick diamond inlay, with only the lower terminus of this finish remaining visible. Historic images show this gable vent was installed pre-1970.

The southwest corner of the structure has been augmented with a one storey addition clad in board and batten siding. The addition has a flat roof that is accessible as a rooftop patio.

Two original single-stack brick chimneys remain, one on the rear and one on the south side adjacent to the cross gable.

The home has two hip roofed dormers, one on the north and one on the south. These dormers do not appear original to the home. The brickwork associated with them is not an exact match for the rest of the structure and the window sills are of cast concrete and are not in keeping with the remainder of the home. The use of hip dormers deviates from the typical gable dormers associated with the Gothic Revival style.

Exterior



Image 1: Front façade of Moody-Darker House, facing west



Image 2: Northeast corner of Moody-Darker House, facing southeast



Image 3: North face of Moody-Darker House, facing south



Image 4: Northwest corner of Moody-Darker House, facing southeast



Image 5: West face of Moody-Darker House, facing east, note board and batten addition with upper balcony



Image 6: South face of Moody-Darker House, facing north



Image 7: Southeast corner of Moody-Darker House, facing northwest



Image 8: Only remaining original wood window, four light awning style in basement window well



Image 9: Bay on south face of structure, note decorative voussoirs and carved key stones




Image 10: Bay window on front façade of Moody-Darker House



Image 11: Close up of dichromatic brick voussoir with carved keystone



Image 12: Close up of voussoirs with decorative cut buff brick finish as used on east and south face of structure



Image 13: Ribbon pointing present in voussoirs




Image 14: Representative example of dichromatic decorative quoining with ribbon pointed mortar



Image 15: Representative example of dichromatic decorative element on second storey




Image 16: Closeup of decorative diamond pattern typical of gables



Image 17: Closeup of brick panels located below structural openings on bays, note extensive water damage to brick and mortar



Image 18: Closeup of remaining ribbon pointing in brick façade



Image 19: Use of modern aluminum fascia, soffit and eavestrough



Image 20: Example of field stone foundation with flush bond mortar



Image 21: Rear of structure showing signs of removal of previous rear addition



Image 22: Aluminum fascia used to cover suspected attachment point of drop pendant decoration



Image 23: Large air vent located in gable end of front façade, note remains of original diamond dichromatic brickwork below grate



Image 24: Hip roof dormer on south side of Moody-Darker House



Image 25: Modification to north dormer of structure, sill is cast concrete and brick work does not match with rest of home



Image 26: Example of cracking in brick veneer



Image 27: Large window on north face of structure, sill has been replaced with cast concrete and voussoir shows signs of deformation



Image 28: Example of typical brick exfoliation resulting from poor water management

5.2 Interior

The interior of the Moody-Darker House has been subject to extensive modification, and as a result no longer presents an original floor plan or with any original finishes. The first floor has been completely replaced, including the removal and replacement of all original floor joists with modern I-joists. The second floor retains its original joists but they have been augmented through the sistering of modern dimensional lumber.

All original fittings have been removed from the structure and replaced with modern sheet goods and MDF trim finishes. The roof structure has been modified to allow for greater headroom and shows signs of rafter replacement with modern, dimensional lumber.

The interior of the structure is in very poor condition due to extensive water damage, resulting in the destruction of the current flooring, wall finishes and trim. The water damage has resulted in extensive mold growth throughout the structure.

The basement has been insulated and exhibits the same water damage present throughout the remainder of the structure.

Overall, the interior of the home displays no heritage attributes and is in need of complete replacement in order to address the water damage and mold issues.

Interior




Image 29: Interior of bay on front of home



Image 30: Extant stairs, note deformation of trim around door resulting from water infiltration



Image 31: Typical example of the interior of structure, facing north



Image 32: Example of modern ceiling and use of recessed lighting



Image 33: Evidence of past renovation, note use of sistered joists



Image 34: Rear hall on first floor, note mould growth and floor damage indicative of extensive water damage, facing west



Image 35: Kitchen on first floor, facing southwest



Image 36: Area where large section of wall has been removed, facing southwest



Image 37: Steel I-beam used to replace structure where wall has been removed




Image 38: Landing on second floor at top of stairs



Image 39: Front room of second floor located in gable end of structure, facing east



Image 40: Modern roof construction on second floor



Image 41: Rear room on second floor, facing north, windows are located in hip dormer depicted in Image 25, note water damage to flooring




Image 42: Water damage typical of that observed on second floor




Image 43: Example of new roof framing



Image 44: Example of new wall framing with original brick behind



Image 45: Stairs to basement



Image 46: Example of original framing with horizontal board sheathing augmented by modern 2x4 framing



Image 47: Basement, facing southwest



Image 48: Typical example of water damage and mould growth in basement



Image 49: Overview of basement



Image 50: I-joists used to replace original floor joists, typical of entire first floor as seen from basement

6. Conservation Principals

All work undertaken at the Moody-Darker House should adhere to established heritage conservation standards. Canada's Historic places has compiled the *Standards and Guidelines for the Conservation of Historic Places in Canada* (2010); hereafter, *CHP Standards and Guidelines*. The standards were compiled in response to international and national agreements including *International Charter for the Conservation and Restoration of Monuments and Sites* (the Venice Charter 1964), *The Australian ICOMOS* (International Council on Monuments and Sites) (the Burra Charter 1979), and the *Canadian Appleton Charter for the Protection and Enhancement of the Built Environment* (1983). In compiling the *CHP Standards and Guidelines*, three standardized conservation treatments (preservation, rehabilitation, and restoration) were formulated that employ 15 Standards reflecting best practices. Through the *CHP Standards and Guidelines*, conservation projects can be accomplished in a way that will ensure the longevity of the heritage resource.

6.1 CHP Standards and Guidelines

The *CHP Standards and Guidelines* are not presented in a hierarchical order and should be given equal consideration.

All Projects

1. Conserve the heritage value of a historic place. Do not remove, replace, or substantially alter its intact or reparable character defining elements. Do not move a part of a historic place if its current location is a character defining element.
2. Conserve changes to a historic place which over time have become character defining elements in their own right.
3. Conserve heritage value by adopting an approach calling for minimal intervention.
4. Recognize each historic place as a physical record of its time, place and use. Do not create a false sense of historical development by adding elements from other historic places or other properties, or by combining features of the same property that never coexisted.
5. Find a use for a historic place that requires minimal or no change to its character defining elements.
6. Protect and, if necessary, stabilize a historic place until any subsequent intervention is undertaken. Protect and preserve archaeological resources in place. Where there is potential for disturbance of archaeological resources, take mitigation measures to limit damage and loss of information.
7. Evaluate the existing condition of character defining elements to determine the appropriate intervention needed. Use the gentlest means possible for an intervention. Respect heritage value when undertaking an intervention.
8. Maintain character defining elements on an ongoing basis. Repair character defining elements by reinforcing their materials using recognized conservation methods. Replace in kind any extensively redecorated or missing parts of character defining elements, where there are surviving prototypes.

9. Make any intervention needed to preserve character defining elements physically and visually comparable with the historic place, and identifiable upon close inspection. Document any intervention for future reference.

Additional Standards for Rehabilitation

10. Repair rather than replace character defining elements. Where character defining elements are too severely deteriorated to repair, and where sufficient physical evidence exists, replace them with new elements that match the forms, materials and detailing of sound versions of the same elements. Where there is insufficient physical evidence make the form material and detailing of the new elements compatible with the character of the historic place.
11. Conserve the heritage value and character defining elements when creating any new additions to a historic place or any related new construction. Make the new work physically and visually compatible with, subordinate to, and distinguishable from the historic place.
12. Create any new additions or related new construction so that the essential form and integrity of a historic place will not be impaired if the new work is removed in the future.

Additional Standards for Restoration

13. Repair rather than replace character defining elements from the restoration period. Where character defining elements are too severely deteriorated to repair and where sufficient physical evidence exists, replace them with new elements that match the forms, materials and detailing of sound versions of the same elements.
14. Replace missing features from the restoration period with new features whose forms, materials, and detailing are based on sufficient physical, documentary and/or oral evidence.

6.2 Qualified Specialists

Employing practitioners with the specialized skills necessary to undertake each aspect of a conservation project will ensure the longevity and sustainability of the heritage resource being addressed. Conservation work should be undertaken by professionals familiar with heritage structures. Undertaking heritage conservation work requires the skills of multiple professions, each of whom specializes in an aspect of the process. The Canadian Association of Heritage Professionals (CAHP) maintains a list of practitioners who focus on the specific skills needed to undertake the restoration and preservation of historic structures. For a list of heritage professions, refer to the Craft and Trade directory on the CAHP website (www.caph-acecp.ca). When selecting a practitioner, one should assess previous examples of their work to ensure their skill set is conducive to the unique circumstances of your specific project. A generalized breakdown of the tasks needed to conserve Moody-Darker House are outline below.

6.3 Moody-Darker House Rehabilitation

A defining principle of the CHP *Standards and Guidelines* is the importance of minimal intervention; in all cases of conservation, one should only do enough, and only enough, to meet realistic objectives of protecting heritage values (CHP 2010:26). The characterization of minimal intervention varies between projects, but always come back to doing only what is required to protect the value of a heritage resource. In the case of Moody-Darker house, in order to conserve the house, it has to be relocated so that it may be rehabilitated at its new site.

According to the *CHP Standards and Guidelines*, rehabilitation should be implemented when:

1. Repair or replacement of deteriorated features is necessary
2. Alteration or additions to the historic place are planned for a new or continued use
3. Depiction during a particular period in its history is not appropriate

6.4 Repair or Replacement of Deteriorating Features

Lists of repairs or replacements of deteriorating features at the Moody-Darker House are listed below.

6.4.1 Masonry Repair

- Stabilize structural cracks
- Repoint the brick work
- Replace damaged and missing bricks
- Repair masonry at structural openings
- Restore dichromatic brickwork in front gable impacted by modern vent installation
- Stabilize and repair chimneys

6.4.2 Roof Repair

- Replace existing asphalt shingle roof with one that mimics cedar shakes or utilize a metal roofing system

6.4.3 Windows and doors

- Restore main and side entrance to original configuration (Images 51 and 52)
- Restore windows to multi light configuration (Image 55)

6.4.4 Facia and Soffit

- Assess if original is present under current aluminum and repair and restore (Image 53)
- If original is missing replace current aluminum with temporally correct wood or similar product that resembles original wood, soffit ventilation must be integrated into restoration

6.4.5 Millwork

- Assess gable ends for signs of missing pendants and decorative finishes. If signs exist, temporally appropriate recreations should be constructed and installed. Image 54 provides an example on a stylistically similar house within the HCD

6.4.6 Veranda

- A temporally sympathetic wrapping veranda should be constructed to replace the existing. The current veranda is concrete and utilizes a wrought iron support structure that is not original and is not in keeping with the style of the home. Image 56 provides an example of a stylistically appropriate veranda design

6.5 Alteration or Additions for Continued Use

The rehabilitation of Moody-Darker house will require the use of modern windows designed to resemble the appearance of the missing originals. The access to the structure may also need to be

adjusted to facilitate continued use as a commercial space and comply with contemporary accessibility laws. Alternative means of egress could be incorporated into the veranda.

6.6 Depiction During a Particular Period

The depiction of the Moody-Darker House at a set point in history is not conducive to the continued use of the structure. A lack of documentation as to the original configuration negates this option.



Image 51: c.1971 image of Moody-Darker House, note original windows and doors



Image 52: c.2000 image detailing original front door and sidelights



Image 53: Original moulded soffit and fascia, date of photo unknown



Image 54: Example of the type of gable detail that may have been present on Moody-Darker House



Image 55: Example of window style that should be used in Moody-Darker House



Image 56: Example of temporally appropriate veranda design, gable decoration is also evident in the image

7. Work to be Undertaken

The scope of relocating and rehabilitating Moody-Darker house will require the use of specialized personnel and adherence to accepted health and safety practices.

Prior to undertaking any work on the Moody-Darker House samples of all materials will need to be presented to and approved by City Heritage Staff. Failure to consult City Heritage Staff will result in project delays and cost overruns. Conservation work review will be undertaken by the City's Building Inspector; Heritage staff may wish to visit the site at their discretion.

7.1.1 Understand and Document Existing Condition

A Phase I Environmental Site Assessment (ESA) should be undertaken to identify and develop mitigation strategies to ensure the health and safety of all workers. Historic structures often contain hazardous materials that must be mitigated to ensure the safety of all subsequent activities. Potential hazards to consider include but are not limited to lead, mould, and asbestos. A Phase I ESA will identify if additional studies are required to mitigate potential hazards. Based on the findings of the ESA, mitigation of the identified issues will need to be undertaken by qualified personnel.

7.1.2 Permitting

Prior to undertaking any work, the appropriate permits will need to be acquired from the City of Vaughn. No heritage specific criteria required; an experienced project manager can accomplish this task.

7.1.3 Stabilization

Prepare the structure for relocation. Fragile elements will need to be stabilized prior to undertaking the relocation. The relocation team will be able to provide a complete list of these elements but must include damaged masonry and chimneys. This work will need to be undertaken congruent with and prior to relocation.

7.1.4 Relocation

Hire a company with extensive experience stabilizing and relocating heritage homes. Ensure the company has sufficient insurance. Heritage specific experience required.

7.1.5 Foundation

Visible surfaces of the new foundation should be tooled to resemble the original field stone foundation (Image 20). Material from the original foundation should be salvaged and reworked to accomplish this. A heritage mason will be able to advise as to how to undertake this work.

7.1.6 Masonry Repair

Utilize a heritage mason to assess and conserve the exterior finish of the structure. Heritage masonry is unique from modern commercial brickwork and requires expertise in the use of traditional lime mortars and unique tooling. Be sure that lime mortar is used in the repair process as modern cement-based mortar is not appropriate for use with heritage masonry. Ensure the mason has experience and specific training in the repair and maintenance of heritage materials. Mason should assess home prior to relocation to ensure current masonry is stable enough to

remain intact during relocation. It may be necessary to undertake some or all repair prior to relocation.

7.1.7 Windows and Doors

All windows and doors should be replicated as per those depicted in Images 51 to 53. Replacement windows should ideally be made of wood and utilize exterior storms. Short of this, the windows should replicate the appearance of original wood divided light double or single hung units (Image 55). The front entrance should be returned to its original configuration including round headed side lights. Prior to ordering windows and doors, material samples will need to be presented to the City of Vaughn for approval. Failure to do so will result in lost time and additional costs.

7.1.8 Millwork

The fascia and soffit should be replaced using traditional materials (wood); discrete soffit vents are acceptable and can be retrofit into original materials. Should original soffit and fascia not exist beneath the current aluminum, alternative materials may be considered that duplicate the appearance of the original (Image 53). The City will need to approve any replacement materials prior to installation. If original wood remains below current aluminum, restoration and repair should be conducted by a heritage carpenter with previous experience working on historic buildings. Repairs should minimize the loss of original material and be constructed of like materials.

7.1.9 Veranda

The extant veranda has undergone extensive alterations. The current veranda is constructed of poured concrete and utilizes wrought iron supports. The concrete and iron veranda should be removed and replaced with one constructed of wood. Based on the roof structure the layout of the veranda appears original and as such the replacement should follow the same footprint, but be constructed of wood and utilize wood support posts with decorative bracketing. Image 56 provides an example of the type of veranda that should be on the house. Veranda restoration should be conducted by a heritage carpenter with previous experience. Any original materials present in the current veranda should be retained for reuse. It is often necessary and even preferable to remove verandas and porches from structures prior to undertaking relocation. Attachments of the veranda to the residence must be done in a way that does not compromise the masonry; attachments should be made to the mortar and not to the brick. Attachment to the brick results in unnecessary damage to the underlying substrate.

7.1.10 Interior

The interior of the structure will need to be completely re-developed. This re-development should integrate interior finishes that are supportive of the antiquity of the home. Interior finishes including baseboards, door and window trim, flooring and interior doors should be supportive of and compatible with the style of the structure. Samples of all interior material will need to be presented to City Heritage Staff for approval prior to commencing work.

8. Intervention Solutions

As outlined in the CHIA (PHC 2021), the preferred mitigation option for the Moody-Darker House is the relocation of the structure to a new site south of its current location (Appendix B). To facilitate this, the Moody-Darker House will be lifted and transported from its current location and re-established on a newly prepared foundation. Following relocation, the structure will undergo conservation of the exterior finishes and re-development of the interior.

8.1 Moving Plan

The relocation of 8204 Kipling Avenue will result in the structure being moved approximately 350 m south of its current location. The relocation will result in the structure being repositioned onto a new poured concrete foundation. The new location is illustrated in Appendix B. The specifics of the moving plan should be provided in advance of the Building Permit Application.

8.2 Cost Estimate

The relocation and rehabilitation of the Moody-Darker house is estimated to cost between \$1,000,000 and \$2,000,000 (Table 1). This cost estimate is anticipated to fluctuate through the course of the stabilization, relocation, and restoration tasks.

9. Schedule of Work

Table 1: Task Importance and Resource Cost Estimate

Phase	Operation	Task	Importance	Responsibility	Resources (estimate)	Description
1	Preparation	Phase I ESA	High	Developer	\$7,500	Identify potential hazards: lead, mould, asbestos
		ESA Remediation	High	Developer	\$15,000 - \$30,000	Remediate any identified hazards
		Permits	Critical Path	Developer	\$5,000 - \$20,000	Secure all necessary permits from City
		Stabilization	High	House Moving Contractor	\$20,000 - \$30,000	Make house ready to lift
		Documentation	Critical Path	Developer	\$5,000	Photo-document all aspects of project
		New Location	High	Developer	\$20,000 - \$50,000	Permits and prep of new location
2	Relocation	Lift and move House	High	House Moving Contractor	\$200,000+	Move house to new location
3	Rehabilitation	Restoration	High	Heritage Trades Specialists	\$200,000+	Repair exterior
		Monitoring	High	Building Inspector	\$5,000	Monitor house during ongoing work
4	Conversion	Adaptive Reuse	Medium	Developer	\$200,000+	Interior restoration work
		Landscaping	Medium	Developer	\$50,000	Ensure property reflects values of HCD

10. Next Steps

Following approval of the Site Development Application and prior to undertaking any work a Building Permit Application will need to be obtained. In filing the Building Permit Application, the following will be required:

- Construction drawings including:
 - Site Plan Drawing at 1:200 scale or larger
 - Summation of conservation work plans as completed by trade specialists
 - Design Plans, including roof (1:50 scale minimum)
 - Section Plans, (1:50 scale minimum)
 - Elevations detailing areas of conservation work (1:50 scale minimum)
 - Construction details outlining materials and detailing work (1:20 scale minimum)
 - Window schedule
- Revised construction schedule
- Approval of material specifications and samples

11. Bibliography and Reference Documents

Blumenson, John

1989 *Ontario Architecture: A Guide to Styles and Building Terms 1784 to the Present*. Fitzhenry & Whiteside, Canada.

City of Vaughan

nd *Village of Woodbridge Fonds*. Electronic resource available online:
[https://www.vaughan.ca/services/vaughan_archives/findingaids/Forms/Village%20of%20Woodbridge%20Fonds%20\(RG%204\).pdf](https://www.vaughan.ca/services/vaughan_archives/findingaids/Forms/Village%20of%20Woodbridge%20Fonds%20(RG%204).pdf) Last accessed 14 April 2021.

2009 *Woodbridge Heritage Conservation District Study and Plan*. Electronic resource available online:
https://www.vaughan.ca/services/business/heritage_preservation/General%20Documents/Woodbridge%20Heritage%20Conservation%20District%20Plan%20and%20Guidelines.pdf Last accessed 16 October 2020.

2017 *Guidelines for the Cultural Heritage Impact Assessments* Electronic resource available online at:
https://www.vaughan.ca/services/business/heritage_preservation/General%20Documents/Guidelines%20for%20CHIA%202017.pdf Last accessed March 2021.

2019a *Official Plan*. Electronic resource available online at:
https://www.vaughan.ca/projects/policy_planning_projects/General%20Documents/Official%20Plan%20Vol%201/VOP%202010%20Updates%202020/VOP%20Volume%201%20Feb%2010%202019.pdf Last accessed March 2021.

2019b *Guidelines for Preparing a Conservation Plan for Heritage resources (CPHR)*. Electronic Resource available at:
https://www.google.com/url?sa=t&rct=j&q=&esrc=s&source=web&cd=&ved=2ahUKEwjgpg_ZufvAhUMZKwKHRGOA_4QFjABegQIBhAD&url=http%3A%2F%2Fwww.vaughan.ca%2Fservices%2Fbusiness%2Fheritage_preservation%2Fheritage_permits_and_clearances%2FForms%2FCPHR%2520Conservation%2520Plan%2520-TOR.pdf&usq=AOvVaw39QsqCSZWbvil6iotX99o Last accessed April 2021

Parks Canada

2010 *Standards & Guidelines for the Conservation of Historic Places in Canada*. Queens Printer, Canada.

Province of Ontario

1990a *Ontario Heritage Act*. Electronic resource available online:
<https://www.ontario.ca/laws/statute/90o18>. Last accessed 21 June 2020.

1990b *Planning Act*. Electronic resource available online:
<https://www.ontario.ca/laws/statute/90p13>. Last accessed 21 June 2020.

2020 *Provincial Policy Statement*. Electronic resource available online:
<https://www.ontario.ca/page/provincial-policy-statement-2020>. Last accessed 4 July 2020.

Regional Municipality of York

2019 *The Regional Municipality of York Official Plan 2019 Office Consolidation* Electronic resource
available online at: https://www.york.ca/wps/wcm/connect/yorkpublic/0dc3cfc2-2e0f-49d2-b523-dc7c14b08273/15001_yropConsolidation2016AccessibleMay42016.pdf?MOD=AJPERES
Last accessed 16 October 2020.

Appendix A



Senior Heritage Specialist – Carla Parslow, PhD, CAHP Member in Good Standing: Dr. Carla Parslow has over 20 years of experience in the cultural heritage resource management (CHRM) industry in Canada. As the President of PHC Inc., Dr. Parslow is responsible for the management of CHRM projects, as well as the technical review and quality assurance of all archaeological and cultural heritage projects completed by PHC. Throughout her career, Carla has managed both large and small offices of CHRM professionals and has mobilized both large (50+) and small (4+) teams of CHRM and Environmental projects offices throughout the province of Ontario. Dr. Parslow has served as either Project Manager or Project Director on hundreds of Archaeological and Cultural Heritage Assessments. Dr. Parslow is a professional member of the Canadian Association of Heritage Professionals (CAHP).

Dr. Parslow is also responsible for the overall quality assurance.

Heritage Specialist – Chris Lemon, B.Sc., Dip. CAHP Member in Good Standing: Chris Lemon is a Cultural Heritage Specialist and Licensed Archaeologist (R289) with 15 years' experience. He received an Honours B.Sc. in Anthropology from the University of Toronto and has completed course work towards an M.A. from the University of Western Ontario. Mr. Lemon has a Diploma in Heritage Carpentry and Joinery and a Certificate in Heritage Planning from Algonquin College. During his career Mr. Lemon has participated in cultural heritage assessments across Ontario as both a Senior Field Director in archaeology and as a Built Heritage Practitioner. Chris's previous experience includes representation on Joint Health and Safety Committees; he is dedicated to maintaining a safety-first focus on all job sites. Chris is a professional member of the Canadian Association of Heritage Professionals (CAHP).

Mr. Lemon is responsible for research, reporting and analysis.

Appendix B




DATE: 18.10.24
PROJECT: KLINGLING COURTARDS
DRAWING: SITE PLAN & STATISTICS
SCALE: 1:100
SHEET: 11 OF 11



ISSUE DATES AND DISTRIBUTION LOG

No.	Date	Issue
1	16.08.24	ISSUED FOR REVISIONS
2	17.07.27	ISSUED FOR REVIEW
3	17.08.08	ISSUED FOR REVIEW
4	17.10.18	ISSUED FOR REVIEW
5	17.10.24	ISSUED FOR REVIEW
6	18.02.07	ISSUED FOR PERMITS REVIEW
7	18.03.21	ISSUED FOR REVISIONS
8	18.08.24	ISSUED FOR PERMITS REVIEW
9	18.11.09	ISSUED FOR REVIEW
10	17.05.14	ISSUED FOR PERMITS REVIEW



SITE STATISTICS

PROPOSED ZONING DESIGNATION	RT1
LOT AREA	13,322.45m ² (3.24ac)

BUILDING INFORMATION:

COVERAGE	AREA (m ²)	PERCENT (%)
TOWNHOUSE BLOCK 'A'	423m ²	(3.2%)
TOWNHOUSE BLOCK 'B'	423m ²	(3.2%)
TOWNHOUSE BLOCK 'C'	423m ²	(3.2%)
TOWNHOUSE BLOCK 'D'	224m ²	(1.7%)
TOWNHOUSE BLOCK 'E'	366m ²	(2.7%)
TOWNHOUSE BLOCK 'F'	366m ²	(2.7%)
EXISTING HERITAGE HOUSE	112m ²	(0.7%)
MIDRISE	1,294m ²	(9.7%)
TOTAL BUILDING COVERAGE	3,637m ²	(27%)
PAVING (HARDSCAPING)	4,655m ²	(35%)
LANDSCAPING (SOFTSCAPING)	3,122m ²	(24%)
FSI (FLOOR SPACE INDEX)	0.73	

STORIES HEIGHT

STORIES	HEIGHT (m)
3	9.7m
3	9.7m
3	9.7m
3	9.7m
3	9.7m
2	8.24m
3	9.64m
2	7.7m

GROSS FLOOR AREA

AREA (m ²)	AREA (sq ft)
TOWNHOUSE BLOCK 'A'	1,149m ² (12,369sf)
TOWNHOUSE BLOCK 'B'	1,149m ² (12,369sf)
TOWNHOUSE BLOCK 'C'	1,149m ² (12,369sf)
TOWNHOUSE BLOCK 'D'	575m ² (6,189sf)
TOWNHOUSE BLOCK 'E'	957.7m ² (10,309sf)
TOWNHOUSE BLOCK 'F'	957.7m ² (10,309sf)
RESIDENTIAL TOTAL	12,175.4m ² (131,055sf)
COMMERCIAL HERITAGE HOUSE	219.7m ² (2,365sf)
TOTAL GFA	12,395.1m ² (133,420sf)

RESIDENTIAL UNIT COUNT

UNIT TYPE	UNIT COUNT	UNIT MIX
TOWNHOUSE BLOCK 'A'	0	0
TOWNHOUSE BLOCK 'B'	0	0
TOWNHOUSE BLOCK 'C'	0	0
TOWNHOUSE BLOCK 'D'	0	0
TOWNHOUSE BLOCK 'E'	0	0
TOWNHOUSE BLOCK 'F'	0	0
TOTAL	0	0

MIDRISE

UNIT TYPE	UNIT COUNT	UNIT MIX
STUDIO	2	3%
1 BEDROOM	12	18%
2 BEDROOM + DEN	32	49%
3 BEDROOM	64	70%
2 BEDROOM TOTAL	1	2%
3 BEDROOM TOTAL	18	2%
TOTAL UNIT COUNT	65	RESIDENTIAL (INCL. 15 TOWNHOUSE UNITS)

OUTDOOR AMENITY AREA RATES

BY-LAW, 1-88 RATE	PROPOSED RATE
RESIDENTIAL	15m ² STUDIO N/A
	25m ² /1 BED UNIT N/A
	35m ² /2 BED UNIT N/A
	60m ² /3 BED UNIT

OUTDOOR AMENITY SPACE: REQUIRED PROPOSED

STUDIO	1BD	2BD	3BD
STUDIO	30m ²	30m ²	
1 BED UNITS	880m ²	880m ²	
2 BED UNITS	55m ²	55m ²	
3 BED UNITS	4,419m ²	2,940m ²	
TOTAL MIN. AMENITY AREA	5,732m ²	3,905m ²	

AMENITY AREAS

AMENITY AREAS	AREA (m ²)
TOTAL SHARED LANDSCAPED AREA	1,578m ²
TOTAL YARD AREA (TOWNHOUSE)	1,346m ²
TOTAL BALCONY AREA (TOWNHOUSE)	305m ²
TOTAL YARD AREA (MIDRISE)	213m ²
TOTAL BALCONY AREA (MIDRISE)	441m ²
TOTAL OUTDOOR AMENITY AREA	3,923m ²
TOTAL INDOOR AMENITY AREA (MIDRISE)	48,748m ²

SNOW STORAGE

REQUIRED	PROPOSED
2% OF LOT AREA	266.20m ² (2%)
	269.9m ² (2%)

PARKING SPACE RATES

BY-LAW, 1-88 RATE	PROPOSED RATES
STREET TOWNHOUSES (BLOCK A-F FRESHOLD TOWNS)	1.5 SPACES/UNIT 2.0 SPACES/UNIT
MIDRISE UNITS	1.5 SPACES/UNIT 1.5 SPACES/UNIT
VISITOR	0.25 SPACES/UNIT 0.25 SPACES/UNIT
OFFICE	3.5 SPACES/100m ² 3.5 SPACES/100m ²

PARKING SPACES: BY-LAW PROPOSED

STALL DIMENSION	BY-LAW	PROPOSED
STALL DIMENSION	2.7m x 6m	2.7m x 6m
HANDICAP STALL DIMENSION	3.7m x 6m	3.7m x 6m
DRIVE AISLE WIDTH	6m	6m

RESIDENTIAL STREET TOWNHOUSES

VISITOR	LIGHT	62
MIDRISE (VISITOR)	16	16
MIDRISE (RESIDENTIAL)	96	97 (INCL. 66/LG)
EXIST. HERITAGE HOUSE (OFFICE)	8	8
TOTAL SPACES	176*	191*

NOTE: * TOTAL PARKING SPACES REQUIRED AND PROPOSED INCLUDES 2 ACCESSIBLE PARKING SPACES.

BICYCLE PARKING SPACE RATES

BY-LAW, 1-88 RATE	PROPOSED RATES
BLOCK TOWNHOUSES (LONG TERM)	0.1 SPACES/UNIT
BLOCK TOWNHOUSES (SHORT TERM)	0.1 SPACES/UNIT
MIDRISE - RESIDENTIAL (LONG TERM)	0.3 SPACES/UNIT
MIDRISE - RESIDENTIAL (SHORT TERM)	0.1 SPACES/UNIT
OFFICE (LONG TERM)	0.1 SPACES/100m ²
OFFICE (SHORT TERM)	0.1 SPACES/100m ² OR 6 SPACES

BICYCLE PARKING SPACES: REQUIRED PROPOSED

RESIDENTIAL BLOCK TOWNHOUSES (SHORT TERM)	3	4
MIDRISE - RESIDENTIAL (LONG TERM)	7	10
MIDRISE - RESIDENTIAL (SHORT TERM)	25	28
TOTAL SPACES	16	20
SHORT TERM	16	20
LONG TERM	26	29

EXISTING HERITAGE HOUSE (OFFICE)

OFFICE (SHORT TERM)	6	6
OFFICE (LONG TERM)	1	1

NOTE: ALL SHORT TERM BICYCLE PARKING ARE PROVIDED AT GRADE. ALL LONG TERM BICYCLE PARKING FOR THE BLOCK TOWNHOUSES ARE PROVIDED WITHIN EACH INDIVIDUAL UNIT. ALL LONG TERM BICYCLE PARKING FOR THE OFFICE BUILDING WILL PROVIDED WITHIN THE BUILDING.

LOCKER STORAGE

RESIDENTIAL	REQUIRED	PROPOSED
MIDRISE - RESIDENTIAL	50	50

SITE SYMBOL LEGEND:

- ▲ PRINCIPLE ENTRANCE (FOR FIRE FIGHTING OFF ACCESS ROUTE)
- ▲ ENTRANCE TO RETAIL OR GRADE REATED RESIDENTIAL UNIT
- ▲ ACCESSIBLE CURB CUT
- ☐ CATCH BASIN
- ☐ MANHOLE
- ☐ FIRE HYDRANT
- ☐ SIAMASE CONNECTIONS
- ☐ BARRIER FREE PARKING SPACE
- ☐ STOP SIGN
- ☐ FIRE ROUTE SIGNAGE
- ☐ LONG TERM BICYCLE PARKING SIGN
- ☐ LIGHT STANDARD/ EXTERIOR POLE FIXTURE
- ☐ WALL MOUNTED EXTERIOR LIGHT FIXTURE
- ☐ PEDESTRIAN CROSSWALK
- ☐ DOWNSPOUT AND SPLASHPAD LOCATION
- ☐ COMMUNITY MAILBOX
- ☐ METER (GROUPED WHERE POSSIBLE)

SITE SIGN LEGEND:

- ACCESSIBLE PARKING SPACE SIGN
- FIRE ROUTE SIGN
- PEDESTRIAN X SIGN
- LONG TERM BICYCLE PARKING SIGN
- STOP SIGN

NOTE: SIGNAGE TO CONFORM TO CITY OF VAUGHAN BY LAW 1-98.

DRAFT WITHOUT PREJUDICE



KLINGLING COURTARDS
LCT Investment Group LTD.
8204 Kipling Ave.
Vaughan, Ontario


SITE PLAN & STATISTICS

Drawn By: VS, Checked By: KB, Project No: 14-153
Date Printed: 2021.02.17 7:42:51 PM, Scale: As indicated, Drawing No: 11 OF 11


Appendix C



MOODY DARKER HOUSE
 8204 KIPLING AVE., N.
 VAUGHAN, ONTARIO



FIRST FLOOR PLAN
 SCALE: 1/4" = 1'-0"




DRAFT IN PROGRESS
 RECORD OF EXISTING
 STRUCTURAL INFORMATION


JOAN BURTT ARCHITECT
 DATE REVISED: AUGUST 11, 2020



MOODY DARKER HOUSE
 8204 KIPLING AVE., N.
 VAUGHAN, ONTARIO




SECOND FLOOR PLAN
 SCALE: 1/4" = 1' - 0"




DRAFT IN PROGRESS
 RECORD OF EXISTING
 STRUCTURAL INFORMATION

JOAN BURTT ARCHITECT
 DATE REVISED: AUGUST 11, 2020

MOODY DARKER HOUSE
 8204 KIPLING AVE., N.
 VAUGHAN, ONTARIO



BASEMENT FLOOR PLAN
 SCALE: 1/4" = 1'-0"



DRAFT IN PROGRESS
 RECORD OF EXISTING
 STRUCTURAL INFORMATION


JOAN BURTT ARCHITECT
 DATE REVISED: AUGUST 11, 2020

Appendix D





_DSC0428



_DSC0429




_DSC0430



_DSC0431



_DSC0432



_DSC0433



_DSC0434



_DSC0435



_DSC0436



_DSC0437




_DSC0438



_DSC0439




_DSC0440



_DSC0441




_DSC0442



_DSC0443



_DSC0444




_DSC0445



_DSC0446




_DSC0447




_DSC0448




_DSC0449



_DSC0450



_DSC0451



_DSC0452



_DSC0453



_DSC0454



_DSC0455



_DSC0456



_DSC0457




_DSC0458



_DSC0459



_DSC0460




_DSC0461




_DSC0462



_DSC0463



_DSC0464




_DSC0465



_DSC0466



_DSC0467



_DSC0468



_DSC0469



_DSC0470



_DSC0471



_DSC0472




_DSC0473



_DSC0474




_DSC0475



_DSC0476



_DSC0477



_DSC0478



_DSC0479



_DSC0480



_DSC0481



_DSC0482



_DSC0483



_DSC0484



_DSC0485



_DSC0486




_DSC0487



_DSC0488




_DSC0489



_DSC0490




_DSC0491



_DSC0492




_DSC0493




_DSC0494



_DSC0495




_DSC0496




_DSC0497




_DSC0498




_DSC0499




_DSC0500



_DSC0501




_DSC0502




_DSC0503




_DSC0504




_DSC0505




_DSC0506




_DSC0507



_DSC0508




_DSC0509




_DSC0510




_DSC0511




_DSC0512




_DSC0513




_DSC0514




_DSC0515




_DSC0516




_DSC0517




_DSC0518




_DSC0519




_DSC0520




_DSC0521



_DSC0522




_DSC0523




_DSC0524




_DSC0525



_DSC0526



_DSC0527



_DSC0528



_DSC0529



_DSC0530



_DSC0531



_DSC0532




_DSC0533



_DSC0534




_DSC0535




_DSC0536



_DSC0537



_DSC0538




_DSC0539




_DSC0540



_DSC0541



_DSC0542



_DSC0543



_DSC0544



_DSC0545




_DSC0546




_DSC0547




_DSC0548



_DSC0549




_DSC0550




_DSC0551




_DSC0552




_DSC0553




_DSC0554




_DSC0555




_DSC0556




_DSC0557



_DSC0558




_DSC0559




_DSC0560




_DSC0561



_DSC0562



_DSC0563



_DSC0564



_DSC0565




_DSC0566



_DSC0567



_DSC0603



_DSC0604



_DSC0605




_DSC0606



_DSC0607




_DSC0608




_DSC0609



_DSC0610



_DSC0611



_DSC0612



_DSC0613



_DSC0614




_DSC0615



_DSC0616



_DSC0617




_DSC0618




_DSC0619



_DSC0620



_DSC0621




_DSC0622



_DSC0623




_DSC0624



_DSC0625




_DSC0626




_DSC0627




_DSC0628



_DSC0629




_DSC0630




_DSC0631



_DSC0632



_DSC0633




_DSC0634



_DSC0635




_DSC0636



_DSC0637

Appendix E






4 EAST ELEVATION
A401 1:50



3 NORTH ELEVATION
A401 1:50



2 WEST ELEVATION
A401 1:50



1 SOUTH ELEVATION
A401 1:50

DO NOT SCALE THE DRAWINGS
CHECK AND VERIFY ALL DIMENSIONS AT THE SITE.
ALL DRAWINGS, SPECIFICATIONS AND RELATED DOCUMENTS ARE THE
COPYRIGHT PROPERTY OF THE CONSULTANT AND MUST BE RETURNED
UPON REQUEST. REPRODUCTION OF DRAWINGS IN PART OR WHOLE
WITHOUT THE PERMISSION OF THE CONSULTANT IS FORBIDDEN.
DRAWINGS ARE NOT TO BE USED FOR CONSTRUCTION UNTIL SIGNED
AND SEALED BY THE CONSULTANT.


NO.	ISSUES	DATE	BY
1	ISSUED FOR OWNER REVIEW	SEPT 12, 2022	BBA

NO.	REVISIONS	DATE	BY
-----	-----------	------	----

PROJECT:
HERITAGE BUILDING

8204 Kipling Ave
Woodbridge, ON, L4L 2A3
EVANS PLANNING

DRAWING:
**BUILDING ELEVATIONS -
EXISTING**



**BARRY BRYAN
ASSOCIATES**

Architects
Engineers
Project Managers

201-250 Water Street
Whitby Ontario L1N 0G5
Tel: (905) 666-5252
Fax: (905) 666-5256
e-mail: bba@bba-arch.com

DESIGN BY:	BBA	DATE:	09/09/22
DRAWN BY:	AJR	CHECKED BY:	DB
SCALE:	1:50	FILE:	Drawings - Current - CECC.RVT


PROJECT NO:

14098.1

DRAWING NO:

A401

Appendix F




- GENERAL MASONRY NOTES:**
1. STABILIZE STRUCTURAL CRACKS
 2. REPOINT THE BRICK WORK
 3. REPLACE DAMAGED AND MISSING BRICKS
 4. REPAIR MASONRY AT STRUCTURAL OPENINGS
 5. RESTORE DICHROMATIC BRICKWORK IN FRONT GABLE IMPACTED BY MODERN VENT INSTALLATION
 6. STABILIZE AND REPAIR CHIMNEYS



4 EAST ELEVATION
A402 1:50

- GENERAL MASONRY NOTES:**
1. STABILIZE STRUCTURAL CRACKS
 2. REPOINT THE BRICK WORK
 3. REPLACE DAMAGED AND MISSING BRICKS
 4. REPAIR MASONRY AT STRUCTURAL OPENINGS
 5. RESTORE DICHROMATIC BRICKWORK IN FRONT GABLE IMPACTED BY MODERN VENT INSTALLATION
 6. STABILIZE AND REPAIR CHIMNEYS



2 WEST ELEVATION
A402 1:50

- GENERAL MASONRY NOTES:**
1. STABILIZE STRUCTURAL CRACKS
 2. REPOINT THE BRICK WORK
 3. REPLACE DAMAGED AND MISSING BRICKS
 4. REPAIR MASONRY AT STRUCTURAL OPENINGS
 5. RESTORE DICHROMATIC BRICKWORK IN FRONT GABLE IMPACTED BY MODERN VENT INSTALLATION
 6. STABILIZE AND REPAIR CHIMNEYS



3 NORTH ELEVATION
A402 1:50

- GENERAL MASONRY NOTES:**
1. STABILIZE STRUCTURAL CRACKS
 2. REPOINT THE BRICK WORK
 3. REPLACE DAMAGED AND MISSING BRICKS
 4. REPAIR MASONRY AT STRUCTURAL OPENINGS
 5. RESTORE DICHROMATIC BRICKWORK IN FRONT GABLE IMPACTED BY MODERN VENT INSTALLATION
 6. STABILIZE AND REPAIR CHIMNEYS



1 SOUTH ELEVATION
A402 1:50

DO NOT SCALE THE DRAWINGS
CHECK AND VERIFY ALL DIMENSIONS AT THE SITE.
ALL DRAWINGS, SPECIFICATIONS AND RELATED DOCUMENTS ARE THE
COPYRIGHT PROPERTY OF THE CONSULTANT AND MUST BE RETURNED
UPON REQUEST. REPRODUCTION OF DRAWINGS IN PART OR WHOLE
WITHOUT THE PERMISSION OF THE CONSULTANT IS FORBIDDEN.
DRAWINGS ARE NOT TO BE USED FOR CONSTRUCTION UNTIL SIGNED
AND SEALED BY THE CONSULTANT.


NO.	ISSUES	DATE	BY
1	ISSUED FOR OWNER REVIEW	SEPT 30, 2022	BBA

NO.	REVISIONS	DATE	BY
-----	-----------	------	----

PROJECT:
HERITAGE BUILDING

8204 Kipling Ave
Woodbridge, ON, L4L 2A3
EVANS PLANNING

DRAWING:
**BUILDING ELEVATIONS -
PROPOSED**



**BARRY BRYAN
ASSOCIATES**

Architects
Engineers
Project Managers

201-250 Water Street
Whitby Ontario L1N 0G5
Tel: (905) 666-5252
Fax: (905) 666-5256
e-mail: bba@bba-archeng.com

DESIGN BY:	CEC	COMPLETE
DRAWN BY:	CEC	COMPLETE
AUTHOR:		
CHECKED BY:		
CHECKER:		
DATE:	09/21/22	
SCALE:	1:50	
FILE:	Drawings - Current - CECC.RVT	

PROJECT NO:
14098.1

DRAWING NO:
A402

© Parslow Heritage Consultancy Inc.

883 St. Clair Avenue West, Rear, Toronto, ON, M6C 1C4

Telephone: [647-348-4887](tel:647-348-4887)

Email: admin@phcgroup.ca

Website: www.phcgroup.ca