

**Vaughan Fire and Rescue Service**  
**Official Call Report**

**ATTACHMENT 5**  
**6701 HIGHWAY 7**

<i>Alarm No</i>	<i>Received</i>	<i>District</i>	<i>City</i>	<i>Platoon</i>
23-0011285	1	73	VAUGHAN	D
<i>R.T.</i>	<i>Prop</i>	<i>Dollar Loss amount</i>		
1	301	\$ 100,000		

<b>Actual Location:</b>	6701	HIGHWAY 7
<b>Call Type:</b>	Fire	
<b>Reported By:</b>	911	
<b>Confirmed Location:</b>		

<b>Date of Call</b>	03/27/2023
<b>Call Received</b>	04:26:36
<b>Notified</b>	04:27:34
<b>Command Establiished</b>	
<b>All Clear</b>	
<b>Fire Control</b>	
<b>Loss Stop</b>	09:57:14

**Unit Details**

	<i>Notified</i>	<i>On Air</i>	<i>On Scene</i>	<i>Cleared</i>
E731	04:27:34	04:29:33	04:32:29	10:20:29

PL736	04:27:34	04:28:32	04:33:24	05:40:08
03/29/2023 08:31:11 solimeng				
736 arrived on scene. I made contact with Command and advised them that were going to hit the hydrant just west of the address on the south side of Highway 7 West. 736 proceeded with a forward lay and then proceeded to set up 736 on the alpha side of the structure. We began flowing water. There was an issue with 736's master stream nozzle. We assisted with getting 767 in location so that they could take over flowing from a master stream. Shortly after, Command made 736 available from the scene.				

CH75	04:27:34	04:30:02	04:33:52	10:24:36
03/29/2023 18:22:56 benbihyj				
York EMS -#3467				
Alectra -Mike Dulman				
Enbridge Gas -Denis Mohammed, 647-273-5758				

<i>Fire Pt Contact</i>	<i>EMS Pt Contact</i>	<i>Keyholder</i>	<i>Ambulance Arrival</i>
<i>Defib Time</i>		<i>Hydro</i>	<i>Police Arrival</i>

**Captain:** Mason, Gary

*Printed:* 07/12/2023 14:44:55

**Platoon Chief:** Benbihy, Jack

# Vaughan Fire and Rescue Service

## Official Call Report

Chief 75 Reported to OFM (Allison O'Donnell).  
She was going to report it in the morning to the Duty Supervisor, Dave Emberlain

E796 04:27:34 04:28:43 04:38:42 06:40:15

03/29/2023 09:39:37 gordonl

E796 arrived on scene and was assigned to be on deck and assist L736 with water supply. DR E796 was assigned accountability. We were reassigned to take our truck to the hydrant to relay pump. At that point L736 was replaced by L767. Once water supply was re-established, the driver was left with the truck at the hydrant and the crew returned to the scene. HY 796 was then assigned accountability. We were on deck for the remainder of the scene, assisting with services and owner reps that arrived on scene as well as hose management. Once the master stream was shut down, we were advised to cease pump relay operations and when water supply was restored from the hydrant to L767 we were cleared.

When we arrived on scene the house was fully involved, E731 was placed in the driveway and L736 was on the eastbound lane of Hwy 7, setting up their master stream.

R759 04:27:34 04:29:54 04:38:52 06:58:29

03/29/2023 07:22:26 tumbern

759 responded to 6701 Hwy #7 for a reported structure fire.

Command was established by 731 Capt (Mason) on arrival.

759 assigned and assisted 731 crew with defensive fire attack on the exterior of the home.

Crew deployed a 45mm handline to the B/C side of the structure and applied water.

Crew was later cleared by command.

Deconed on scene and cleared to station.

E756 04:27:34 04:29:45 04:40:00 05:50:18

E741 04:31:17 04:33:15 04:46:27 05:14:14

**Fire Pt Contact**

**EMS Pt Contact**

**Keyholder**

**Ambulance Arrival**

**Defib Time**

**Hydro**

**Police Arrival**

**Captain:** Mason, Gary

**Printed:** 07/12/2023 14:44:55

**Platoon Chief:** Benbihy, Jack

# Vaughan Fire and Rescue Service

## Official Call Report

PL767 04:33:55 04:35:51 04:47:18 10:20:32

03/29/2023 09:58:27 boyesr

767 responded emerge from station for a second alarm structure fire at 6701 Hwy 7.

767 arrived on location without incident.

767 staged level 1.

767 was assigned by command to set up the platform for defensive aerial operations on Hwy 7.

FF Little and FF Woods set up the platform and performed pumping operations.

A/C Boyes and FF Ferguson went up in the platform to apply water with the master stream. We had heavy flames through the roof and all windows of the structure.

Agent application.

767 also supplied 731 with water.

767 flowed water for roughly 2.5 hrs. at 3000L/min(1450kpa) until relieved by the incoming day crew (B platoon).

CH74 04:39:12 04:39:16 04:49:19 07:43:58

T744 04:35:02 04:38:53 04:49:41 05:14:14

T774 04:34:34 04:41:44 04:53:51 05:18:12

CH73 05:31:48 05:31:48 05:59:43 08:48:25

### Call Remarks

Entered by V7474 On 2023-03-27 04:27:34 6701 HIGHWAY 7 W Entered by V7474 On 2023-03-27 04:36:35 CH75 Entered by V7474 On 2023-03-27 04:39:12 6701 HIGHWAY 7 W Entered by V7711 On 2023-03-27 04:42:08 VM ARNOLD Entered by V7474 On 2023-03-27 04:45:53 10 Entered by V7474 On 2023-03-27 04:56:27 20MIN Entered by V7711 On 2023-03-27 04:58:35 MOFFATT Entered by V7711 On 2023-03-27 05:01:33 ETA 45 MINUTES Entered by V7474 On 2023-03-27 05:06:29 30 MIN Entered by V7474 On 2023-03-27 05:15:52 40 MIN Entered by V7474 On 2023-03-27 05:25:37 50 MIN Entered by V7474 On 2023-03-27 05:31:48 6701 HIGHWAY 7 W Entered by V7474 On 2023-03-27 05:36:17 60 MIN Entered by V7404 On 2023-03-27 06:51:46 6701 HIGHWAY 7 W Entered by V7711 On 2023-03-27 04:27:05 IN THE AREA NEAR COSTCO Entered by V7711 On 2023-03-27 04:27:22 FULLY INVOLVED ON SECOND FLOOR Entered by V7711 On 2023-03-27 04:27:45 647-549-6092 Entered by V7711 On 2023-03-27 04:28:07 HONDA CIVIC LEAVING THE SCENE Entered by V7711 On 2023-03-27 04:28:38 YRP TOOK CALLER BACK TO QUESTION REGARDING VEHICLE LEAVING THE HOME Entered by V7711 On 2023-03-27 04:29:34 JUST WEST OF 427 Entered by V7711 On 2023-03-27 04:30:25 SOUTH SIDE OF THE ROAD Entered by V7711 On 2023-03-27 04:33:40 EMS TIERED Entered by V7474 On 2023-03-27 04:35:31 POSSIBLY ABANDONED

Fire Pt Contact

EMS Pt Contact

Keyholder

Ambulance Arrival

Defib Time

Hydro

Police Arrival

Captain: Mason, Gary

Printed: 07/12/2023 14:44:55

Platoon Chief: Benbihiy, Jack

# Vaughan Fire and Rescue Service

## Official Call Report

STRUCTURE Entered by V7474 On 2023-03-27 04:37:54 YRP REQ TO CLOSE HWY 7 EB WEST OF THE SCENE  
Entered by V7474 On 2023-03-27 04:39:52 BLDG IS COLLAPSING Entered by V7711 On 2023-03-27 04:47:06 YRP  
HAVE CLOSED HWY7 BETWEEN NEW HUNTINGTON AND HWY50 Entered by V7474 On 2023-03-27 04:48:07  
PRIMARY SEARCH NOT COMPLETED...NO INDICATION OF OCCUPANTS Entered by V7474 On 2023-03-27  
04:48:58 736 MASTER STREAM BEING USED DEFENSIVE OPERATIONS Entered by V7474 On 2023-03-27 05:00:43  
HYDRO ETA WITHIN THE HOUR Entered by V7474 On 2023-03-27 05:11:29 741 ADDED AT 0431 BY DISPATCHER  
FOR WORKING FIRE RESPONSE Entered by V7474 On 2023-03-27 05:12:32 DISPATCHER ADDED 744 AND 774  
TO CALL WHEN IT WAS REPORTED THAT THERE WERE NO HYDRANTS IN AREA...THIS MAY HAVE DELAYED  
RESPONSE OF 771 AND 741 AS THEY HAD ALREADY BEEN DISPATCHED AT THAT POINT Entered by V7474 On  
2023-03-27 05:36:48 INCIDENT TIME CLOCK STOPPED Entered by V7474 On 2023-03-27 06:09:46 PROPERTY  
OWNER ON SCENE Entered by V7404 On 2023-03-27 07:03:24 POWER ISOLATED Entered by V7514 On  
2023-03-27 07:36:42 FP KHAZAI-NEJAD WILL BE ATTENDING SCENE Entered by V7404 On 2023-03-27 08:22:53  
FLAMES IN GARAGE Entered by V7404 On 2023-03-27 09:15:26 EXCIVATOR KNOCKING DOWN PARTS OF HOME  
- PUTTING OUT HOT SPOTS Entered by V7404 On 2023-03-27 10:24:31 SCENE LEFT WITH PROPERTY OWNER

03/29/2023 08:56:57 masong

731 responded, emergency, from station 73 to the dispatched area without incident, from Hwy 7 and Hwy 27 we could see large orange glow in the distant with large volume of black smoke. On our arrival we had a medium sized 2 story residential farmhouse with fire showing from both stories of the residence, I assumed Hwy 7 command in defensive strategy.

-731 entered the driveway, locked gate across the driveway, FF. J. Rice used the eDraulic O cutter to cut the chain, I opened the gate and 731 proceeded to the delta side of the structure. I completed a 360 of the residence, 2 stories from the Charlie side with no determination of a basement, main floor was showing fire in all windows but the garage on the delta side was not involved with fire on our arrival. Second floor showed fire in all but 2 windows, large volume of black smoke was exiting those windows. Mini van was parked in front of the garage, it was not plated. Transfer of command report was giving to chief 75, chief 75 assumed Hwy 7 command, remaining in defensive strategy, I reverted to 731 Captain.

-731 crew pulled 65mm hand line to the alpha side, agent application, in the kitchen and living room through the windows, I completed another 360 of the structure and reported that fire was now in the roof and the structure was starting to collapse.

-See truck narratives for other assignments on scene.

-731 remained on location until relieved by 73 B Platoon crew.

<i>Fire Pt Contact</i>	<i>EMS Pt Contact</i>	<i>Keyholder</i>	<i>Ambulance Arrival</i>
<i>Defib Time</i>		<i>Hydro</i>	<i>Police Arrival</i>

**Captain:** Mason, Gary

*Printed:* 07/12/2023 14:44:55

**Platoon Chief:** Benbihiy, Jack