ITEM: 6.9

REPORT SUMMARY MINOR VARIANCE APPLICATION FILE NUMBER A070/25

Report Date: Friday, July 4, 2025

THIS REPORT CONTAINS COMMENTS FROM THE FOLLOWING DEPARTMENTS & AGENCIES (SEE SCHEDULE B):

Additional comments from departments and agencies received after the publication of the report will be made available on the City's <u>website</u>.

Internal Departments *Comments Received	Conditions Required		Nature of Comments
Committee of Adjustment	Yes □	No ⊠	General Comments
Building Standards (Zoning)	Yes □	No ⊠	General Comments
Development Planning	Yes □	No □	Application Under Review
Development Engineering	Yes □	No ⊠	General Comments
Development Finance	Yes □	No ⊠	General Comments
Forestry	Yes □	No □	Recommend Adjournment

External Agencies *Comments Received	Conditions Required		Nature of Comments *See Schedule B for full comments
Alectra	Yes □	No ⊠	General Comments
Region of York	Yes □	No ⊠	General Comments
TRCA	Yes ⊠	No □	General Comments w/Conditions

PUBLIC & APPLICANT CORRESPONDENCE (SEE SCHEDULE C)

All personal information collected because of this public meeting (including both written and oral submissions) is collected under the authority of the Municipal Act, the Municipal Freedom of Information and Protection of Privacy Act (MFIPPA), the Planning Act and all other relevant legislation, and will be used to assist in deciding on this matter. All personal information (as defined by MFIPPA), including (but not limited to) names, addresses, opinions and comments collected will become property of the City of Vaughan, will be made available for public disclosure (including being posted on the internet) and will be used to assist the Committee of Adjustment and staff to process this application.

Correspondence Type	Name	Address	Date Received (mm/dd/yyyy)	Summary
Applicant			06/24/2025	Arborist Report
Applicant			06/24/2025	Landscape Plan
Applicant			06/24/2025	Tree Inventory Report

BACKGROUND (SCHEDULE D, IF REQUIRED)	
* Background Information contains historical development approvals considered to be related to this file.	
This information should not be considered comprehensive.	
Application No. (City File)	Application Description
.,	(i.e. Minor Variance Application; Approved by COA / OLT)
N/A	N/A
	1717

ADJOURNMENT HISTORY		
* Previous hearing dates where this application was adjourned by the Committee and public notice issued.		
Hearing Date		Reason for Adjournment (to be obtained from NOD_ADJ)
N/A N/A		

SCHEDULES	
Schedule A	Drawings & Plans Submitted with the Application
Schedule B	Comments from Agencies, Building Standards & Development Planning
Schedule C (if required)	Public & Applicant Correspondence
Schedule D (if required)	Background



MINOR VARIANCE APPLICATION FILE NUMBER A070/25

CITY WARD #:	2
APPLICANT:	Rosalee Bello
AGENT:	Evaristo Jardin (Turner Fleischer Architects Inc)
PROPERTY:	145 Waymar Heights Boulevard, Woodbridge
ZONING DESIGNATION:	See below.
VAUGHAN OFFICIAL PLAN (2010) DESIGNATION:	Vaughan Official Plan 2010 ('VOP 2010'): "Low Rise Residential" by Schedule 2 - Land Use Plan of Woodbridge Centre Secondary Plan (Chapter 11.11, Volume 2)
RELATED DEVELOPMENT APPLICATIONS:	N/A
PURPOSE OF APPLICATION:	Relief from the Zoning By-law is being requested to permit the construction of a new dwelling, cabana, porch and widened driveway.

The following variances have been requested from the City's Zoning By-law:

The subject lands are zoned R1E(EN) – First Density Zone (Established Neighbourhood) under Zoning By-law 001-2021, as amended.

#	Zoning By-law 001-2021	Variance requested
1	The minimum front yard shall be 17.63 metres. [Table 7-3]	To permit a minimum front yard of 13.0 metres.
2	The maximum building height shall be 8.5 metres. [4.5]	To permit a maximum building height of 9.74 metres.
3	A porch including stairs may encroach a maximum 2.0 metres into a required front yard. [Table 4-1]	To permit a porch including stairs to encroach a maximum of 2.44 metres into the required front yard.
4	The maximum height of a residential accessory building shall be 3.0 metres. [4.14]	To permit a residential accessory building to have a maximum height of 3.41 metres.
5	The maximum driveway width shall be 9.0 metres. [6.7]	To permit a maximum driveway width of 10.8 metres.

HEARING INFORMATION

DATE OF MEETING: Thursday, July 10, 2025

TIME: 6:00 p.m.

MEETING LOCATION: Vaughan City Hall, Woodbridge Room (2nd Floor), 2141 Major Mackenzie Drive

LIVE STREAM LINK: Vaughan.ca/LiveCouncil

PUBLIC PARTICIPATION

If you would like to speak to the Committee of Adjustment at the meeting, either remotely or in person, please complete the Request to Speak Form and submit to cofa@vaughan.ca

If you would like to submit written comments, please quote file number above and submit by mail or email to:

Email: cofa@vaughan.ca

Mail: City of Vaughan, Office of the City Clerk, Committee of Adjustment, 2141 Major Mackenzie Drive, Vaughan, ON, L6A 1T1

To speak electronically, pre-registration is required by completing the Request to Speak Form on-line and submitting it to cofa@vaughan.ca no later than NOON on the last business day before the meeting.

THE DEADLINE TO REGISTER TO SPEAK ELECTRONICALLY OR SUBMIT WRITTEN COMMENTS ON THE ABOVE NOTED FILE(S) IS <u>NOON</u> ON THE LAST BUSINESS DAY BEFORE THE MEETING.

INTRODUCTION

Staff and Agencies act as advisory bodies to the Committee of Adjustment. The comments contained in this report are presented as recommendations to the Committee.

Section 45(1) of the Planning Act sets the criteria for authorizing minor variances to the City of Vaughan's Zoning By-law. Accordingly, review of the application may consider the following:

That the general intent and purpose of the by-law will be maintained.

That the general intent and purpose of the official plan will be maintained.

That the requested variance(s) is/are acceptable for the appropriate development of the subject lands. That the requested variance(s) is/are minor in nature.

Public written and oral submissions relating to this application are taken into consideration by the Committee of Adjustment as part of its deliberations and final decision on this matter.

COMMITTEE OF ADJUSTMENT		
Date Public Notice Mailed:	June 16, 2025	
Date Applicant Confirmed Posting of Sign:	June 13, 2025	
Applicant Justification for Variances: *As provided in Application Form	We are providing a similar setback to the newer homes recently constructed adjacent to and across the road from 145 Waymar Heights.	
Was a Zoning Review Waiver (ZRW) Form submitted by Applicant: *ZRW Form may be used by applicant in instances where a revised submission is made, and zoning staff do not have an opportunity to review and confirm variances prior to the issuance of public notice.		

COMMENTS:

On June 24, 2025, Parks, Forestry and Horticulture Operations staff stated, "Forestry is now in receipt of the arborist report for this property, we are requesting adjournment of the file so we may evaluate the significant trees on site for potential preservation, this may result in required design changes."

On June 24, 2025, Development Planning staff stated, "Planning staff concurs with Forestry staff in that additional time is required to review the materials recently provided.

Environmental Planning staff have advised that the subject property contains and is adjacent to "Core Features" (i.e. significant forest, bioforest features) of the Natural Heritage Network (NHN) as identified by the Vaughan Official Plan. The Core Feature, in this case being the woodland to the property's rear, needs to be identified through a dripline staking. A 10 m vegetation protection zone buffer is required for Core Features of the NHN.

Environmental Planning staff needs to be satisfied that the proposed tree removals are not impacting the Core Feature, and that should impacts be proposed, necessary mitigation measures are taken to protect the Core Feature.

It would be difficult to justify that the minor variance proposal meets the general intent of the Vaughan Official Plan without this analysis. I'll be in touch to provide you detailed comments and requirements from Environmental Planning staff in the coming days. In the meantime, please request adjournment to the next cycle."

On June 24, 2025, Committee of Adjustment staff requested the applicant to adjourn the application, due to the requests made by the Parks, Forestry and Horticulture Operations and the Development Planning departments. The applicant was advised of the potential adjournment fee. The applicant chose to proceed to the July 10, 2025, Committee of Adjustment Hearing.

On June 24, 2025 the applicant confirmed that they wanted to proceed to the July 10 hearing.

Committee of Adjustment Recommended	If the application is to be adjourned from July 10th,
Conditions of Approval:	2025, hearing, a \$640.00 adjournment fee will be
	applicable.

BUILDING STANDARDS (ZONING)	
**See Schedule B for Building Standards (Zoning) Comments	
Building Standards Recommended Conditions of Approval: None	

DEVELOPMENT PLANNING		
**See Schedule B for Development Planning	g Comments.	
Development Planning Recommended Conditions of Approval:	TBD	

DEVELOPMENT ENGINEERING

<u>Link to Grading Permit</u> <u>Link to Pool Permit</u> <u>Link to Curb Curt Permit</u> <u>Link Culvert Installation</u>

The proposed single storey residential dwelling can increase to the existing storm drainage flows having adverse effects on the neighbour's property. The Owner/Applicant must submit an application and obtain an approved Grading Permit prior to starting any work on the property related to the proposed two-storey dwelling. The Owner/Applicant is responsible for ensuring that positive drainage is maintained and that the construction does not create any surface drainage issues on adjacent private or public lands, in accordance with the City of Vaughan's Engineering Standards.

The Owner/Applicant shall submit an application and obtain an approved Grading Permit before initiating any work on the property. The Final Lot Grading and/or Servicing Plan will be required for the Grading Permit Application. Please visit the Permits page of the City of Vaughan's website: Permits | City of Vaughan to apply for a Grading Permit. For any inquiries regarding the Grading Permit, please email DEPermits@vaughan.ca

The Owner / Applicant shall apply for a Pool Permit with the Development Engineering (DE) Department. Please visit the grading permits page at City of Vaughan website to learn how to apply for the Pool Permit. If you have any question about Pool Grading Permit, please contact the Development Engineering Department through email at DEPermits@vaughan.ca.

The Owner / Applicant shall submit an application for a Road Occupancy Permit for the proposed modification to the existing circular driveway. Applications for the permit can be submitted either by email to Utility.Coordinator@vaughan.ca or in person at the Joint Operations Center located at 2800 Rutherford Road. The Owner / Applicant is responsible for restoring all affected areas, including ditches and boulevards, to their original condition. For instructions on applying for the Road Occupancy Permit, please refer to the Road Occupancy Permit, Municipal Consent and Road Closure Application | City of Vaughan page on the City of Vaughan website.

For your proposed modification of an existing circular driveway, the Roads Operations Department installs and replaces culverts for Vaughan residents and businesses. All culvert work within the municipal right-of-way requires City approval and coordination. To apply for new culvert installation or replacement, you must call Service Vaughan at 905-832-2281.

The Transportation and Fleet Management Services maintains and repairs ditches and culverts. Your project will require coordination with this department since it involves both culvert removal and installation affecting the municipal drainage system. The Owner / Applicant shall apply and obtain the necessary Culvert/Reinstating Permit. For instructions on applying for the Culvert/Reinstating Permit, please refer to the Curb Cuts and Driveway Widening | City of Vaughan page on the City of Vaughan website.

The Development Engineering Department does not object to the Minor Variance application A070/25.

The Development Engineering Department	does not object to the Millor variance application Actor25.
Development Engineering	None
Recommended Conditions of	
Approval:	

PARKS, FORESTRY & HORTICULTURE (PFH)				
Time required to process tree preservation potential on site.				
PFH Recommended Conditions of Approval: None				

DEVELOPMENT FINANCE		
No comment no concerns		
Development Finance Recommended Conditions of Approval:	None	

BY-LAW AND COMPLIANCE, LICENSING AND PERMIT SERVICES			
No comments received to date.			
BCLPS Recommended Conditions of Approval: None			

BUILDING INSPECTION (SEPTIC)			
No comments received to date.			
Building Inspection Recommended Conditions of Approval: None			

FIRE DEPARTMENT			
No comments received to date.			
Fire Department Recommended Conditions of Approval:	None		

RECOMMENDED CONDITIONS OF APPROVAL SUMMARY

Should the Committee find it appropriate to approve this application in accordance with request and the sketch submitted with the application, as required by Ontario Regulation 200/96, the following conditions have been recommended:

#	DEPARTMENT / AGENCY	CONDITION
1	Development Planning	TBD
	Harry.zhao@vaughan.ca	
2	TRCA	That the applicant provides the required fee
	yorkplan@trca.ca	amount of \$660.00 payable to the Toronto and
		Region Conservation Authority.

All conditions of approval, unless otherwise stated, are considered to be incorporated into the approval "if required". If a condition is no longer required after an approval is final and binding, the condition may be waived by the respective department or agency requesting conditional approval. A condition cannot be waived without written consent from the respective department or agency.

IMPORTANT INFORMATION

CONDITIONS: It is the responsibility of the owner/applicant and/or authorized agent to obtain and provide a clearance letter from respective department and/or agency (see condition chart above for contact). This letter must be provided to the Secretary-Treasurer to be finalized. All conditions must be cleared prior to the issuance of a Building Permit.

APPROVALS: Making any changes to your proposal after a decision has been made may impact the validity of the Committee's decision.

An approval obtained from the Committee of Adjustment, where applicable, is tied to the building envelope shown on the plans and drawings submitted with the application and subject to the variance approval.

A building envelope is defined by the setbacks of the buildings and/or structures shown on the plans and drawings submitted with the application, as required by Ontario Regulation 200/96. Future development outside of an approved building envelope, where a minor variance was obtained, must comply with the provisions of the City's Zoning By-law.

Elevation drawings are provided to reflect the style of roof (i.e. flat, mansard, gable etc.) to which a building height variance has been applied. Where a height variance is approved, building height is applied to the style of roof (as defined in the City's Zoning By-law) shown on the elevation plans submitted with the application.

Architectural design features that are not regulated by the City's Zoning By-law are not to be considered part of an approval unless specified in the Committee's decision.

DEVELOPMENT CHARGES: That the payment of the Regional Development Charge, if required, is payable to the City of Vaughan before issuance of a building permit in accordance with the Development Charges Act and the Regional Development Charges By-law in effect at the time of payment.

That the payment of the City Development Charge, if required, is payable to the City of Vaughan before issuance of a building permit in accordance with the Development Charges Act and the City's Development Charges By-law in effect at the time of payment.


That the payment of the Education Development Charge if required, is payable to the City of Vaughan before issuance of a building permit in accordance with the Development Charges Act and the Boards of Education By-laws in effect at the time of payment

IMPORTANT INFORMATION

That the payment of Special Area Development charge, if required, is payable to the City of Vaughan before issuance of a building permit in accordance with the Development Charges Act and The City's Development Charge By-law in effect at the time of Building permit issuance to the satisfaction of the Reserves/Capital Department.

NOTICE OF DECISION: If you wish to be notified of the decision in respect to this application or a related Ontario Land Tribunal (OLT) hearing you must complete a Request for Decision form and submit to the Secretary Treasurer (ask staff for details). In the absence of a written request to be notified of the Committee's decision you will **not** receive notice.

SCHEDULE A: DRAWINGS & PLANS







Created By: Infrastructure Delivery Department May 21, 2025 10:39 AM

Projection: NAD 83 UTM Zone

Legend


MUNICIPAL OFFICES

COMMUNITY CENTRES

SCHOOLS



Catholic Private



LIBRARIES

SHOPPING CENTRES

ENTERTAINMENT & CULTURE

Parcels



PROPOSED SINGLE RESIDENTAIL DWELLING

145 Waymar Heights, Vaughan, ON


25.085P01

	DRAWING LIST
DSG100	SURVEY PLAN
DSG101	SITE PLAN
DSG150	BASEMENT
DSG151	FLOOR 01
DSG152	FLOOR 02
DSG153	ROOF
DSG154	EAST AND WEST ELEVATIONS
DSG155	MORTH AND SOUTH ELEVATIONS
DSG155A	(ELEVATIONS CABANA)
DSG156	SECTIONS
DSG157	SECTIONS



REISSUED FOR COA 2025-05-30

Phone Number: 416-425-2222 ext Email: first.last@turnerfleischer.com








RECEIVED

By russog at 2:00 pm, Jun 04, 2025




FLOOR 1
CABANA
176.95


ESTABLISH
GRADE CABANA
176.82

1 EAST SIDE ELEVATION ACCESSORY BUILDING Copy 1

NORTH SIDE ELEVATION ACCESSORY BUILDING Copy 1
1:50



3 SOUTH SIDE ELEVATION ACCESSORY BUILDING Copy 1



WEST SIDE ELEVATION ACCESSORY BUILDING Copy 1

0SG155A 1:50



67 Lesmill Road Toronto, ON, M3B 2T8 T 416 425 2222 turnerfleischer.com

The issuance of this record drawing is a representation by Turner Fleischer that the construction, enlargement or alteration of the building is in general, as opposed to precise, conformitly with the design prepared and provided by Turner Fleischer, but is not a representation that the construction, enlargement or alteration of the building is in conformity with a design that has been prepared or provided by others. The revisions to these contract documents, reflecting the significant changes in the work made during construction, are based on data furnished by the contractor to Turner Fleischer. Turner Fleischer shall not be held responsible for the accuracy or completeness of the information provided by the contractor.

3 2025-06-04 REISSUED FOR COA YPS
2 2025-05-30 REISSUED FOR COA YPS
1 2025-05-14 ISSUED FOR COA AND TRCA YPS
DATE DESCRIPTION BY

PROPOSED SINGLE RESIDENTAIL
DWELLING

145 Waymar Heights, Vaughan, ON

DRAWING

ELEVATIONS CABANA

PROJECT NO.
25.085P01
PROJECT DATE

PROJECT NO.

25.085P01

PROJECT DATE

2025-05-13

DRAWN BY

HST


CHECKED BY

YPS

SCALE

1:50

DSG155A REV.



SCHEDULE B: COMMENTS FROM AGENCIES, BUILDING STANDARDS & DEVELOPMENT PLANNING

Internal Departments *Comments Received	Conditions Required		Nature of Comments
Building Standards (Zoning)	Yes □	No ⊠	General Comments
Development Planning	Yes □	No □	Application Under Review

External Agencies *Comments Received	Conditions Required		Nature of Comments *See Schedule B for full comments	
Alectra	Yes □	No ⊠	General Comments	
Region of York	Yes □ No ⊠		General Comments	
TRCA	Yes ⊠	No □	General Comments w/Conditions	



Date: June 10th 2025

Attention: Sean Fitzpatrick

RE: Request for Comments

File No.:

Related Files: A070-25

Applicant: Turner Fleischer Architects Inc

Location 145 Waymar Heights Boulevard



COMMENTS:

	We have reviewed the proposed Variance Application and have no comments or objections to its approval.
X	We have reviewed the proposed Variance Application and have no objections to its approval, subject to the following comments (attached below).
	We have reviewed the proposed Variance Application and have the following concerns (attached below).

Alectra Utilities (formerly PowerStream) has received and reviewed the proposed Variance Application. This review, however, does not imply any approval of the project or plan.

All proposed billboards, signs, and other structures associated with the project or plan must maintain minimum clearances to the existing overhead or underground electrical distribution system as specified by the applicable standards, codes and acts referenced.

In the event that construction commences, and the clearance between any component of the work/structure and the adjacent existing overhead and underground electrical distribution system violates the Occupational Health and Safety Act, the customer will be responsible for 100% of the costs associated with Alectra making the work area safe. All construction work will be required to stop until the safe limits of approach can be established.

In the event construction is completed, and the clearance between the constructed structure and the adjacent existing overhead and underground electrical distribution system violates the any of applicable standards, acts or codes referenced, the customer will be responsible for 100% of Alectra's cost for any relocation work.

References:

- Ontario Electrical Safety Code, latest edition (Clearance of Conductors from Buildings)
- Ontario Health and Safety Act, latest edition (Construction Protection)
- Ontario Building Code, latest edition (Clearance to Buildings)
- PowerStream (Construction Standard 03-1, 03-4), attached
- Canadian Standards Association, latest edition (Basic Clearances)

If more information is required, please contact either of the following:

Mr. Stephen Cranley, C.E.T

Supervisor, Distribution Design, ICI & Layouts (North)

Phone: 1-877-963-6900 ext. 31297

E-mail: stephen.cranley@alectrautilities.com

Mitchell Penner

Supervisor, Distribution Design-Subdivisions

Phone: 416-302-6215

Email: Mitchell.Penner@alectrautilities.com




Power Stream 1

Construction Standard

03-1

	SYSTEM VOLTAGE						
LOCATION OF WIRES, CABLES OR CONDUCTORS	SPAN GUYS AND COMMUNICATIONS WIRES		4.16/2.4kV TO 27.6/16kV (SEE NOTE 1)	44kV			
	MINIMUM	MINIMUM VERTICAL CLEARANCES (SEE NOTE 2)					
OVER OR ALONGSIDE ROADS, DRIVEWAYS OR LANDS ACCESSIBLE TO <u>VEHICLES</u>	442cm	442cm	480cm	520cm			
OVER GROUND ACCESSIBLE TO PEDESTRIANS AND BICYCLES ONLY	250cm	310cm	340cm	370cm			
ABOVE TOP OF RAIL AT RAILWAY CROSSINGS	730cm	730cm	760cm	810cm			



MINIMUM ATTACHMENT HEIGHT = MAXIMUM SAG

- + MINIMUM VERTICAL CLEARANCE (FROM ABOVE TABLE)
 ± GRADE DIFFERENCE

- + 0.3m (VEHICLE OR RAILWAY LOCATION) + SNOW DEPTH (PEDESTRIAN LOCATION, SEE NOTE 3)

NOTES:

- THE MULTIGROUNDED SYSTEM NEUTRAL HAS THE SAME CLEARANCE AS THE 600V SYSTEM.
- 2. THE VERTICAL CLEARANCES IN THE ABOVE TABLE ARE UNDER $\underline{\text{MAXIMUM SAG}}$ CONDITIONS.
- 3. REFER TO CSA STANDARD C22.3 No.1, ANNEX D FOR LOCAL SNOW DEPTH
- 4. ALL CLEARANCES ARE IN ACCORDANCE TO CSA STANDARD C22.3.

<u>\G</u>	340cm	11'-4"					
	310cm	10'-4"					
VALUES.	250cm	8'-4"					
VALUES.							
REFERENCES							
SAGS AND T	FNSIONS 1	SECTION 02					

METRIC

810cm

760cm 730cm

520cm 480cm

442cm 370cm

CONVERSION TABLE

IMPERIAL (APPROX)

27'-0" 25'-4"

24'-4" 17'-4"

15'-5" 12'-4"

MINIMUM VERTICAL CLEARANCES OF WIRES, CABLES AND CONDUCTORS ABOVE GROUND OR RAILS


ORIGINAL ISSUE DATE: 2010-DEC-24 REVISION NO: R1 REVISION DATE: 2012-JAN-09


Certificate of Approval This construction Standard meets the safety requirements of Section 4 of Regulation 22/04						
Joe Crozier, P.Eng. 2012-JAN-09 Name Date						
P Fng Annroyal By: Ine Crozier						



Construction Standard

03 - 4





VOLTAGE	MINIMUM HORIZONTAL CLEARNACE UNDER MAXIMUM SWING CONDITIONS DIMENSION "X" (SEE NOTES 1, 3 & 4)	MINIMUM VERTICAL CLEARANCE UNDER MAXIMUM DESIGN SAG CONDITIONS DIMENSION "Y" (SEE NOTES 1, 2, 4 & 5)
0-600V AND NEUTRAL	100cm	250cm
4.16/2.4 TO 44kV	300cm	480cm

NOTES

- UNDER NO CIRCUMSTANCES SHALL A CONDUCTOR BE PERMITTED TO PENETRATE THE ENVELOPE SHOWN BY THE DOTTED LINE.
- 2. THE VERTICAL CLEARANCES ARE UNDER CONDITIONS OF MAXIMUM DESIGN SAG.
- THE HORIZONTAL CLEARANCES ARE UNDER CONDITIONS OF MAXIMUM SWING. WHERE THE CONDUCTOR SWING IS NOT KNOWN A HORIZONTAL CLEARANCE OF 480CM SHALL BE USED.
- 4. BUILDINGS THAT EXCEED 3 STOREYS OR 15M IN HEIGHT, THE MINIMUM HORIZONTAL CLEARANCE OF THE SECONDARY CONDUCTORS SHOULD BE INCREASED TO 300cm WHERE IT IS NECESSARY TO ALLOW FOR THE RAISING OF LADDERS BY LOCAL FIRE DEPARTMENTS.
- IN SITUATIONS SUCH AS MULTI-LEVEL GARAGES, WHERE ROOFS ARE NORMALLY USED BY PERSONS AND VEHICLES, THE VERTICAL CLEARANCES OF POWERSTREAM STANDARD 03-1 SHALL APPLY.
- 6. DISTRIBUTION LINES CONSTRUCTED NEAR BUILDINGS SHALL BE BUILT TO AVOID OVERHANG WHEREVER POSSIBLE. WHERE LINES MUST BE CONSTRUCTED OVER OR ADJACENT TO BUILDINGS THE APPLICABLE HORIZONTAL AND VERTICAL CLEARANCES SHALL BE AT CONDITIONS OF MAXIMUM CONDUCTOR SWING AND MAXIMUM SAG. THE ABOVE CLEARANCES ARE DESIGNED TO PREVENT PERSONS ON OR IN BUILDINGS AS WELL AS EXTERNAL MACHINERY USED IN CONJUCTION WITH A BUILDING TO COME IN CONTACT WITH CONDUCTORS. EFFORTS SHOULD BE MADE TO INCREASE THESE CLEARANCES WHERE POSSIBLE.
- 7. ALL CLEARANCES ARE IN ACCORDANCE TO CSA C22.3 NO.1-06 (TABLE-9).

ON TABLE
IMPERIAL
(APPROX)
16'-0"
10'-0"
8'-4"
3'-4"

MINIMUM VERTICAL & HORIZONTAL CLEARANCES OF CONDUCTORS FROM BUILDINGS OR OTHER PERMANENT STRUCTURES (CONDUCTORS NOT ATTACHED TO BUILDINGS)

ORIGINAL ISSUE DATE: 2010—MAY—05 REVISION NO: REVISION DATE:
PEgystem Planning and Standards/Standard Design/PowerStream Standards/working (abbr/Scellan 3/3-4/c/wg d3-4 Ro May 5, 2010, s/wg, 3/3/2010 8/2022 AM, Adobe POF



To: Committee of Adjustment

From: Sean Fitzpatrick, Building Standards Department

Date: June 09, 2025

Applicant: TURNER FLEISCHER ARCHITECTS INC

Location: 145 Waymar Heights Boulevard

PLAN RP4134 Lot 21

File No.(s): A070/25

Zoning Classification:

The subject lands are zoned R1E(EN) – First Density Zone (Established Neighbourhood) under Zoning By-law 001-2021, as amended.

#	Zoning By-law 001-2021	Variance requested
1	The minimum front yard shall be 17.63 metres .	To permit a minimum front
	[Table 7-3]	yard of 13.0 metres.
2	The maximum building height shall be 8.5 metres . [4.5]	To permit a maximum
		building height of 9.74
		metres.
3	A porch including stairs may encroach a maximum 2.0	To permit a porch including
	metres into a required front yard. [Table 4-1]	stairs to encroach a
		maximum of 2.44 metres
		into the required front yard.
4	The maximum height of a residential accessory building	To permit a residential
	shall be 3.0 metres . [4.14]	accessory building to have a
		maximum height of 3.41
		metres.
5	The maximum driveway width shall be 9.0 metres. [6.7]	To permit a maximum driveway
		width of 10.8 metres.

Staff Comments:

Stop Work Order(s) and Order(s) to Comply:

There are no outstanding Orders on file

Building Permit(s) Issued:

Building Permit No. 25-111038 for Single Detached Dwelling - Residential Demolition, Issue Date: May 01, 2025

Other Comments:

Ge	General Comments						
1	The applicant shall be advised that additional variances may be required upon review of						
	detailed drawing for building permit/site plan approval.						
2	The subject lands may be subject to Ontario Regulation 166/06 (TRCA - Toronto and						
	Region Conservation Authority.						

Conditions of Approval:

If the committee finds merit in the application, the following conditions of approval are recommended.

^{*} Comments are based on the review of documentation supplied with this application.



June 20, 2025. PAR-DPP-2025-00809

SENT BY E-MAIL: Christine.Vigneault@vaughan.ca

Christine Vigneault
Secretary Treasurer
Committee of Adjustment
City of Vaughan
2141 Major Mackenzie Drive
Vaughan, Ontario L6A 1T1

Dear Christine:

Re: Minor Variance Application A070/25
Lot 21, Plan RP4134
145 Waymar Heights Blvd
City of Vaughan, Regional Municipality of York
Applicant: Turner Fleischer Architects Inc (Owner: Rosalee Bello)

This letter acknowledges receipt of the above-noted application circulated by the City of Vaughan. The materials were received by Toronto and Region Conservation Authority (TRCA) on June 10, 2025. TRCA staff have reviewed the application and offer the following comments for the consideration of the Committee of Adjustment.

Purpose of the Application

It is our understanding that the purpose of the above noted application is to request the following variances under By-Law 001-2021:

By-Law 001-2021:

- To permit a minimum front yard of 13.0 metres;
- To permit a maximum building height of 9.74 metres;
- To permit a porch including stairs to encroach a maximum of 2.44 metres into the required front yard;
- To permit a residential accessory building to have a maximum height of 3.41 metres, and;
- To permit a maximum driveway width of 10.8 metres.

The noted variances are being requested to facilitate a replacement two-storey dwelling, cabana in the rear yard, an in-ground pool, and associated hard landscaping and grading.

Ontario Regulation 41/24

The subject property is within TRCA's Regulated Area of the Humber River Watershed due to a valley corridor at the rear of the subject lands. In accordance with Ontario Regulation 41/24, development, interference or alteration may be permitted in the Regulated Area where it can be demonstrated to TRCA's satisfaction that the control of flooding, erosion, dynamic beaches. unstable soils, or bedrock will not be affected.

Application-Specific Comments

TRCA staff have reviewed and issued a permit for the proposed replacement dwelling, cabana, in-ground pool, and associated hard landscaping and grading in the rear yard (TRCA Permit No. PER-DPP-2025-01006, issued June 18, 2025). The plans submitted with this application are consistent with the plans that were approved as part of TRCA's permit.

Based on the above, TRCA staff have no concerns with the proposed variance.

By copy of this letter, the applicant is advised that the TRCA has implemented a fee schedule for our planning application review services. This application is subject to a \$660.00 (Minor Variance – Residential - Minor) review fee. The applicant is responsible for fee payment and should forward the application fee to this office as soon as possible.

Recommendations

Based on the comments noted above, TRCA has no objection to the approval of Minor Variance Application A070/25 subject to the following conditions:

1. That the applicant provides the required fee amount of \$660.00 payable to the Toronto and Region Conservation Authority.

We trust these comments are of assistance. Should you have any questions, please contact me at 437-880-1925 or at cameron.mcdonald@trca.ca.

Sincerely,

Cameron McDonald

Cameron McDonald

Planner I

Development Planning and Permits I Development and Engineering Services cameron.mcdonald@trca.ca, 437-880-1925

From: <u>Development Services</u>

To: <u>Committee of Adjustment Mailbox</u>

Subject: [External] RE: A070/25 - 145 WAYMAR HEIGHTS- REQUEST FOR COMMENTS, CITY OF VAUGHAN

Date: Thursday, June 12, 2025 9:07:54 AM

CAUTION! This is an external email. Verify the sender's email address and carefully examine any links or attachments before clicking. If you believe this may be a phishing email, please use the Phish Alert Button.

Good morning,

The Regional Municipality of York has completed its review of the above minor variance application and has no comments.

Regards,

.

Gabrielle Hurst MCIP, RPP

Associate Planner, Development Planning, Economic and Development Services Branch Corporate Services Department

The Regional Municipality of York | 17250 Yonge Street | Newmarket, ON L3Y 8V3 **O:** 905-830-4444 ext. 71538 | <u>developmentservices@york.ca</u> |

Our Mission: Working together to serve our thriving communities – today and tomorrow

For more information check us out at $\underline{www.york.ca/developmentservices}$

From: Planning Services

To: <u>Committee of Adjustment Mailbox</u>

Subject: [External] RE: A070/25 - 145 WAYMAR HEIGHTS- REQUEST FOR COMMENTS, CITY OF VAUGHAN

Date: Monday, June 16, 2025 5:09:32 PM

Attachments: <u>image001.png</u>

CAUTION! This is an external email. Verify the sender's email address and carefully examine any links or attachments before clicking. If you believe this may be a phishing email, please use the Phish Alert Button.

Hello,

Thank you for the circulation. YRDSB has no objections to the Zoning By-law amendments raised. If further information or clarification is required, please contact this office.

Best regards,

Matthew Lee

Planner, Planning Services
York Region District School Board
matthew.lee@yrdsb.ca

905-727-0022 Ext. 2091



SCHEDULE C: PUBLIC & APPLICANT CORRESPONDENCE

Correspondence Type	Name	Address	Date Received (mm/dd/yyyy)	Summary
Applicant			06/24/2025	Arborist Report
Applicant			06/24/2025	Landscape Plan
Applicant			06/24/2025	Tree Inventory Report



May 30, 2025

ARBORIST REPORT 145 Waymar Heights Boulevard, Vaughan, Ontario

BACKGROUND

MHBC was retained to conduct an inventory of the existing trees within the boundaries of the property known as 145 Waymar Heights Boulevard, as they pertain to the City of Vaughan Tree By-laws. This investigation examined 35 trees within and around the subject property. Field work was completed April 30, 2025, and this report relates to the condition of the trees at that time.

PROCEDURE

The on-site inventory of existing trees was carried out using the current survey of the property and relies on the accuracy of this survey. The inventory includes all trees within the site boundary, all trees within 6.0 metres of the site boundary and all City owned trees along the adjacent boulevards.

This inventory is summarized graphically in the Tree Inventory Plan TI-1, which shall always be read in conjunction with this report and shall form part of this report. For the purposes of this report, trees and groupings of trees are identified in terms of species, size, condition, and recommendations.

The following rating system was used in describing the general condition of the trees inventoried:

Good: Indicates a condition of vigor and no major concerns.


Fair: Indicates an adequate tree, which may have some minor issues. Poor: Indicates declining health, bad form, or other more serious issues.

Dead: Indicates a dead tree that should be removed.

ASSUMPTIONS AND LIMITING CONDITIONS

- Care has been taken to obtain all information from reliable sources. All data has been verified insofar as possible and is assumed to be correct; however, MHBC can neither guarantee nor be responsible for the accuracy of information provided by others.
- It is assumed that the properties are not in violation of any applicable codes, ordinances, statutes, or other governmental regulations.
- Unless otherwise required by law, possession of this report or a copy thereof does not imply right of publication or use for any purpose in whole or in part by any other than the person or company by whom it was commissioned.
- The use of excerpts from this report or alterations to this report, without the authorization of MHBC Planning will invalidate the entire report. This report may not be used for any purpose other than its intended purpose as outlined.





Arborist Report MHBC

• Unless expressed otherwise: 1) information contained in this report covers only those items that were examined and reflect the condition of those items at the time of inspection; and 2) the inspection is limited to visual examination or accessible items without dissection, excavation, probing, or coring. There is no warranty or guarantee, expressed or implied, that problems or deficiencies in the plants inventoried may not arise in the future.

• The determination of ownership of any subject tree(s) is the responsibility of the owner and any civil or common-law issues, which may exist between property owners with respect to trees, must be resolved by the owner. The recommendation to remove or maintain any tree(s) does not grant authority to encroach in any manner onto adjacent private properties.

SUMMARY OF TREES INVENTORIED

Tree #	Common Name	Botanical Name	DBH (CM)	Condition	Comments	Recommendation
201	Norway Maple	Acer platanoides	68	F/P	Obvious significant internal rot, major structural defects evident, tree is potentially hazardous	Remove due to proposed paved area, and poor structural condition
202	Norway Spruce	Picea abies	61	F	Moderate deadwood on north side of tree	Remove
203	Norway Maple	Acer platanoides	30	F/P	Internal rot evident, main leader is dead	Remove
204	Norway Maple	Acer platanoides	46	F	Mild phototropic lean	Remove
205	Norway Maple	Acer platanoides	31	F	Minor deadwood in canopy	Remove
206	Norway Maple	Acer platanoides	26	F/G	Mild to moderate lean	Remove
207	Flowering Crabapple Tree	Malus Sp.	39	F/P	Moderate to significant deadwood in canopy	Retain
208	Norway Maple	Acer platanoides	24	F	Mild lean	Remove
209	White Oak	Quercus alba	50	F	Minor deadwood in canopy	Retain (injure)
210	Sugar Maple	Acer saccharum	25	P/D	Top is dead	Retain
211	Black Walnut	Juglans nigra	64	F/G	Minor deadwood in canopy	Retain
212	Norway Maple	Acer platanoides	21	F/P	Poor structure, irregular form	Remove
213	Norway Maple	Acer platanoides	21	G	Elevated canopy	Remove
214	Norway Maple	Acer platanoides	47	F	Minor to moderate in canopy, mild lean	Remove
215	Sugar Maple	Acer saccharum	28	F	Minor to moderate deadwood in canopy	Retain

3 MHBC

216	Norway Maple	Acer platanoides	52	F	Minor deadwood in canopy, co-dominant leaders	Remove
217	White Spruce	Picea glauca	51	F/P	Tree has been topped due to major structural failure	Remove
218	White Spruce	Picea glauca	51	F	Minor needle drop	Retain
219	Colorado Blue Spruce	Picea pungens var. glauca	33	F	Co-dominant leaders, moderate needle cast	Remove
220	Norway Maple	Acer platanoides	93	Р	Significant structural issues, significant deadwood in canopy, internal rot columns suspected due to cavitation, significant bark inclusion	Remove due to proposed house, and due to structural condition
221	Flowering Crabapple Tree	Malus Sp.	32	Р	Significant internal rot, profusion of water shoots throughout, insect infestation evident, structural issues evident, multi-stem	Remove due to condition
222	Norway Spruce	Picea abies	80	F/G	Minor needle loss	Retain
223	Norway Maple	Acer platanoides	71	Р	Significant internal rot, high likelihood of significant structural failure due to significant rot at main union	Remove due to condition
224	Paper Birch	Betula papyrifera	46	F/P	Significant internal rot visible at base throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident	Remove due to condition
225	Honey Locust	Gleditsia triacanthos	74	F	Minor to moderate deadwood in canopy	Remove
01	Norway Maple	Acer platanoides	~28	F	2 stem at 1.0 metre, moderate damage to northerly stem	Retain
02	Norway Maple	Acer platanoides	~34	F	Boundary tree, growing in fence	Retain
О3	Norway Maple	Acer platanoides	30	F	3 stem at base, minor to moderate deadwood throughout	Retain
04	Norway Maple	Acer platanoides	32	F/G		Retain
O5	Norway Maple	Acer platanoides	44	F/G	Mild bow in trunk	Retain
06	Norway Maple	Acer platanoides	35	F/G	Minor to moderate deadwood in canopy	Retain

Arborist Report MHBC

07	Black Locust	Robinia pseudoacacia	57	F/P	Moderate deadwood in canopy, with structural issues developing	Retain
08	Black Locust	Robinia pseudoacacia	72	F/P	2 stem at 0.4 metres, moderate to significant deadwood in canopy, structural issues evident	Retain
09	White Spruce	Picea glauca	42	F/G	Minor deadwood in canopy	Retain
010	White Spruce	Picea glauca	46	F/G	Minor deadwood in canopy	Retain

The above table summarizes the on-site trees as inventoried. The trees proposed for retention will be subject to tree protection measures per City of Vaughan ULA 110A Heavy Duty and ULA 110B Light Duty Tree Hoarding Protection Fencing Details as outlined on drawings 2-TI-1 and 3-TI-1. It is noted that not all trees marked for retention require tree protection hoarding. Refer to TI-1 for size and layout of tree protection hoarding.

145 Waymar Heights Boulevard, Vaughan, ON Arborist Report 5 MHBC

PHOTO RECORD



Tree 201



Tree 201



Tree 201



Tree 201

rborist Report MHB0



Trees 202, 204, 205, O1, O2



Trees 203, O3 – O6



Trees 206, 207, O7, O8



Trees 208 – 212




Trees 211, 212



Trees 213 - 216



Trees 217, 218



Tree 219



Tree 220



Tree 220



Tree 221



Tree 221



Tree 221



Tree 222




Tree 222



Tree 222



Tree 222



Tree 222



Tree 224



Tree 225

17 MHBC 145 Waymar Heights Boulevard, Vaughan, ON Arborist Report



Trees O9, O10

Arborist Report MHBC

TREE PROTECTION RECOMMENDATIONS

The following standards shall apply to any trees that are identified to be retained. Where the municipality enforces its own standards, those of the governing municipality shall supersede the recommendations contained herein. In all other instances, the following recommendations shall be treated as minimum standards for tree protection and retention.

1.0 ESTABLISH A TREE PROTECTION ZONE

The purpose of the tree protection zone is to prevent root damage, soil compaction and soil contamination during construction activities. Workers and machinery shall not disturb the tree protection zone in any way. In order to prevent access, the following recommendations are offered.

- Install tree protection hoarding as per City of Vaughan ULA 110A Heavy Duty and ULA 110B Light Duty Tree Protection Hoarding Fencing details 2-TI-1 and 3-TI-1.
- Allow no fill, equipment, supplies, or waste within the tree protection zone.
- Maintain the tree protection hoarding in good condition for the duration of construction.
- Tree protection hoarding is not to be removed until all construction activities have been completed.

2.0 ROOT PRUNING

Where possible, hand dig areas closest to each tree to prevent any unnecessary tearing or pulling of roots. Removal of roots that are greater than 2.5 centimeters in diameter or roots that are injured or diseased should be performed as follows:

- Preserve the root bark ridge (similar in structure to the branch bark ridge). Directional Root
 Pruning (DRP) is the recommended technique and should be employed during hand
 excavation around tree roots. Roots are similar to branches in their response to pruning
 practices. With DRP, objectionable and severely injured roots are properly cut to a lateral
 root that is growing downward or in a favorable direction.
- All roots needing to be pruned or removed shall be cut cleanly with sharp hand tools, by a Certified Arborist.
- No wound dressings or pruning paint shall be used to cover the ends of each cut.
- All roots requiring pruning shall be cut using any of the following tools:
 Large or small loppers, Hand pruners, Small hand saws, Wound scribers
- Avoid prolonged exposure of tree roots during construction keep exposed roots moist and dampened with mulching materials, irrigation or wrap in burlap if exposed for longer than 4 hours.

3.0 FERTILIZATION AND IRRIGATION

The following measures are recommended:

- Aeration and deep root fertilize to ensure that all trees receive the appropriate nutrients for healthy growth.
- Fertilizer must be a low nitrogen formula such as *5-30-30* to promote root growth rather than shoot growth.
- If construction occurs during July and / or August, roots must be irrigated during conditions of drought.

Arborist Report MHBC

4.0 ESTABLISH MAINTENANCE PROGRAM

Pre-Construction:

• Prune all trees to remove any deadwood and obstruction prune as required.

During Construction:

- Irrigate tree preservation zones during drought conditions (June through September), in an attempt to reduce the effects of drought stress.
- Inspect the site every month to ensure that all tree protection fence / hoarding is in place and in good condition, inspect the trees to monitor condition.

Post-Construction:

- Prune crowns to remove any newly developed deadwood only. Do not remove any live growth.
- Inspect the trees three times per year (May, July, and September) to monitor condition for a minimum period of 2 additional years.

5.0 LANDSCAPING

Any landscaping completed within the tree preservation zones, after construction is completed and tree protection fencing / hoarding has been removed, is to be carried out in such a way that it will not cause damage to any of the trees or their roots. The trees must be protected to the same standards listed earlier in this report, but without the use of tree protection fence or hoarding.

The following guidelines are recommended:

- No grade changes are permitted which include adding and/or removing soil.
- No excavation is permitted that can cause damage to the roots of the tree.
- No heavy equipment can be used to compact the soil within the tree preservation zone.
- Where possible, hard surface paving around trees to be protected should be constructed using permeable products such as interlocking stone. Areas to be paved must be hand dug when encroaching within the tree protection zone.

CONCLUSIONS

Based on our investigations, we are of the opinion that Trees #201-206, 208, 212-214, 216, 217, 219, 220, and 225 will require removal to accommodate the proposed construction. Trees #221, 223 and 224 will require removal due to their poor condition and potential hazard. Tree #209 will require an injury in order to accommodate the proposed construction. No tree shall be harmed or removed prior to applying for and receiving the requisite permits from the City of Vaughan.

The Tree Protection Costs for this proposed project are \$3,400.00

Tree protection methods must be followed according to City of Vaughan's Tree Protection By-law 052-2018. Tree protection shall be installed as outlined in the arborist report / TPP prior to the commencement of any construction/demolition activities. The tree protection barriers shall be installed at their approved location and shall be maintained in their original location and condition until all construction activities within the site have ceased and all equipment is removed from the site. No equipment or material storage, flushing of fuel or washing of equipment is allowed within the TPZ. Any works within the TPZ area to be performed or supervised by a Certified Arborist. It is our opinion that the trees slated for retention can be successfully retained by following the recommendations set out in this report.

Arborist Report MHB0


Should you have any questions regarding this report, please contact the undersigned directly.

Respectfully submitted,

MHBC Planning, Urban Design & Landscape Architecture

Nick A. Miele BLA, OALA, CSLA, ISA Partner | Landscape Architect | Arborist

ISA Certified Arborist No. ON-1251A




N69°14'25"E 177.190 🖔 🚡 🕳 EGHTS 45'-11 1/4" 14'-5 3/8" 25'-7 7/8" (REQ. SETBACK AT 17.53M) 176.300 N74°41'55"E TREE INVENTORY, PROTECTION, AND REMOVALS PLAN

Note: When 1800mm drip line distance is not attainable, hoarding should be at least. 3000mm from outside UNDISTURBED SOIL VOOD SUPPORT-TAKES; Note: All Support Stake and Hoarding Posts to b wood 2" x 4" member. Note: All Plywood to be 4'x8' sheets. Note:All Connection WOOD SUPPORTS; --Attachment of fence to trees to be preserved is not . Ensure fence is continuous and is located beyond the DEVELOPMENT PLANNING DEPT drip line of trees to be preserved. . Fencing to be installed prior to start of construction. URBAN DESIGN DIVISION All supports and bracing should be inside the Tree Protection Zone. All such supports should HEAVY DUTY TREE HOARDING minimize damaging roots outside the Tree PROTECTION DETAIL (PLYWOOD) Protection Barrier. No Construction activity, grade changes, surface treatment or excavations of any kind is permitted within the Tree Protection Zone. AWN & DESIGNED: URBAN DESIGN

HEAVY DUTY TREE HOARDING PROTECTION DETAIL

TI-1 CITY OF VAUGHAN STANDARD

SCALE: 1:200



TRFF INVENTORY NOTES

Tree #	Common Name	Botanical Name	DBH (CM)	Condition	Comments	Recommendation
201	Norway Maple	Acer platanoides	68	F/P	Obvious significant internal rot, major structural defects evident, tree is potentially hazardous	Remove due to proposed paved area, and poor structural conditi
202	Norway Spruce	Picea abies	61	F	Moderate deadwood on north side of tree	Remove
203	Norway Maple	Acer platanoides	30	F/P	Internal rot evident, main leader is dead	Remove
204	Norway Maple	Acer platanoides	46	F	Mild phototropic lean	Remove
205	Norway Maple	Acer platanoides	31	F	Minor deadwood in canopy	Remove
206	Norway Maple	Acer platanoides	26	F/G	Mild to moderate lean	Remove
207	Flowering Crabapple Tree	Malus Sp.	39	F/P	Moderate to significant deadwood in	Retain
208	Norway Maple	Acer platanoides	24	F	Mild lean	Remove
209	White Oak	Quercus alba	50	F	Minor deadwood in canopy	Retain (injure)
210	Sugar Maple	Acer saccharum	25	P/D	Top is dead	Retain
211	Black Walnut	Juglans nigra	64	F/G	Minor deadwood in canopy	Retain
212	Norway Maple	Acer platanoides	21	F/P	Poor structure, irregular form	Remove
213	Norway Maple	Acer platanoides	21	G	Elevated canopy	Remove
214	Norway Maple	Acer platanoides	47	F	Minor to moderate in canopy, mild lean	Remove
215	Sugar Maple	Acer saccharum	28	F	Minor to moderate deadwood in canopy	Retain
216	Norway Maple	Acer platanoides	52	F	Minor deadwood in canopy, co- dominant leaders	Remove
217	White Spruce	Picea glauca	51	F/P	Tree has been topped due to major structural failure	Remove
218	White Spruce	Picea glauca	51	F	Minor needle drop	Retain
219	Colorado Blue Spruce	Picea pungens var.	33	F	Co-dominant leaders, moderate needle	Remove
		glauca			cast Significant structural issues, significant	Remove due to
					deadwood in canopy, internal rot	proposed house
220	Norway Maple	Acer platanoides	93	Р	columns suspected due to cavitation,	and due to
					significant bark inclusion	structural conditi
					Significant internal rot, profusion of	
The same and			122	224	water shoots throughout, insect	Remove due to
221	Flowering Crabapple Tree	Malus Sp.	32	Р	infestation evident, structural issues	condition
					evident, multi-stem	
222	Norway Spruce	Picea abies	80	F/G	Minor needle loss	Retain
					Significant internal rot, high likelihood	Remove due to
223	Norway Maple	Acer platanoides	71	Р	of significant structural failure due to	condition
					significant rot at main union	condition
					Significant internal rot visible at base	
20.4			40	5/0	throughout tree, moderate to significant	Remove due to
224	Paper Birch	Betula papyrifera	46	F/P	throughout tree, moderate to significant deadwood in canopy, coppice growth	Remove due to
224	Paper Birch	Betula papyrifera	46	F/P	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures	Remove due to
224	Paper Birch	Betula papyrifera	46	F/P	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident	Remove due to
224	Paper Birch Honey Locust	Betula papyrifera Gleditsia triacanthos	46 74	F/P F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures	Remove due to
·			70000	******	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage	Remove due to condition
225	Honey Locust Norway Maple	Gleditsia triacanthos Acer platanoides	74	F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem	Remove due to condition Remove Retain
225 01 02	Honey Locust Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides Acer platanoides	74 ~28 ~34	F F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate	Remove due to condition Remove Retain Retain
225 01 02 03	Honey Locust Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides Acer platanoides Acer platanoides	74 ~28 ~34 30	F F F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence	Remove due to condition Remove Retain Retain Retain
225 O1 O2 O3	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides Acer platanoides Acer platanoides Acer platanoides Acer platanoides	74 ~28 ~34 30	F F F F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout	Remove due to condition Remove Retain Retain Retain Retain
225 01 02 03	Honey Locust Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides Acer platanoides Acer platanoides	74 ~28 ~34 30	F F F	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in	Remove due to condition Remove Retain Retain Retain
225 01 02 03 04 05 06	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides	74 ~28 ~34 30 32 44 35	F F F F/G F/G F/G	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in canopy Moderate deadwood in canopy, with	Remove due to condition Remove Retain Retain Retain Retain Retain Retain Retain
225 O1 O2 O3 O4 O5	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides Acer platanoides Acer platanoides Acer platanoides Acer platanoides Acer platanoides	74 ~28 ~34 30 32 44	F F F F/G F/G	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in canopy Moderate deadwood in canopy, with structural issues developing	Remove due to condition Remove Retain Retain Retain Retain Retain Retain
225 O1 O2 O3 O4 O5 O6	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Black Locust	Gleditsia triacanthos Acer platanoides Acer platanoides	74 ~28 ~34 30 32 44 35	F F F F/G F/G F/G F/P	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in canopy Moderate deadwood in canopy, with structural issues developing 2 stem at 0.4 metres, moderate to	Remove due to condition Remove Retain Retain Retain Retain Retain Retain Retain Retain
225 01 02 03 04 05 06	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple	Gleditsia triacanthos Acer platanoides	74 ~28 ~34 30 32 44 35	F F F F/G F/G F/G	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in canopy Moderate deadwood in canopy, with structural issues developing 2 stem at 0.4 metres, moderate to significant deadwood in canopy,	Remove due to condition Remove Retain Retain Retain Retain Retain Retain Retain
225 01 02 03 04 05 06	Honey Locust Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Norway Maple Black Locust	Gleditsia triacanthos Acer platanoides Acer platanoides	74 ~28 ~34 30 32 44 35	F F F F/G F/G F/G F/P	throughout tree, moderate to significant deadwood in canopy, coppice growth evident at base, past structural failures evident Minor to moderate deadwood in canopy 2 stem at 1.0 metre, moderate damage to northerly stem Boundary tree, growing in fence 3 stem at base, minor to moderate deadwood throughout Mild bow in trunk Minor to moderate deadwood in canopy Moderate deadwood in canopy, with structural issues developing 2 stem at 0.4 metres, moderate to	Remove due to condition Remove Retain Retain Retain Retain Retain Retain Retain Retain

NOTE:

ALL NORWAY MAPLES WITHIN TRCA REGULATED AREA ARE PROPOSED FOR REMOVAL, AND ARE TO BE REPLACED WITH NATIVE SPECIES PER LANDSCAPE PLAN.



EXISTING DECIDUOUS TREE TO REMAIN

LEGEND


EXISTING DECIDUOUS TREE TO BE REMOVED (REFER TO

EXISTING CONIFEROUS TREE TO REMAIN

ARBORIST REPORT)




EXISTING CONIFEROUS TREE TO BE REMOVED (REFER TO ARBORIST REPORT)



TREE IDENTIFICATION KEY (TREES TO BE RETAINED)

TREE IDENTIFICATION KEY (TREES TO BE REMOVED)



HEAVY DUTY TREE PROTECTION FENCING PER CITY OF VAUGHAN STANDARDS

LIGHT DUTY TREE PROTECTION FENCING PER CITY OF VAUGHAN STANDARDS

GENERAL NOTES

- 1. Do not scale the drawings. All dimensions are in millimetres unless noted otherwise.
- 2. This drawing is to be read in conjunction with the project site plan. landscape plan, and engineering plan.
- 3. The tree inventory includes assessment of trees >10cm DBH. The trees have been assessed based on species, size and condition.
- 4. The contractor shall check and verify all existing and proposed grading and conditions on the project and immediately report any discrepancies to the consultant before proceeding with any removals.
- 5. The contractor is to be aware of all existing and proposed services and utilities. The contractor is responsible for having all underground services and utility lines staked by each agency having jurisdiction prior to commencing work.
- 6. This drawing is to be used for development approval only.
- 7. Do not leave any holes open overnight.
- 8. Keep area outside construction zone clean and useable by others at all times. Contractor shall throughly clean areas surrounding the construction zone at the end of each work day.
- 9. Contractor to make good any and all damages outside of the development area that may occur as a result of tree removals at no extra cost.
- 10. This drawing is Copyright MHBC, 2025.

MAY 30, 2025 **ISSUED FOR REVIEW** DATE **ISSUED / REVISION REVISION NO.**





DRAWN BY PLAN SCALE 1:200 FILE NO. 25113A CHECKED BY

NOT FOR CONSTRUCTION All drawings and specifications are instruments of service and will remain the property of MHBC Planning and must be returned at the completion of the work. This drawing shall not be used for construction purposes unless the drawings are marked 'Issued for Construction' and the professional seal is signed and dated by the landscape architect.

N.M.

MAY 2025

PROJECT

FILE NAME

145 WAYMAR HEIGHTS **BOULEVARD** VAUGHAN, ONTARIO

DWG NO.

TREE INVENTORY, PROTECTION, AND **REMOVALS**

TI-1

LIGHT DUTY TREE HOARDING PROTECTION DETAIL

CITY OF VAUGHAN STANDARD

SCHEDULE D: BACKGROUND

• • •		Application Description (i.e. Minor Variance Application; Approved by COA / OLT)		
	N/A	N/A		