IANROBERTSONDESIGN

RECEIVED


By Christine Vigneault at 12:35 pm, Jul 31, 2024


20 RIVERMEDE ROAD, UNIT 101 CONCORD, ON. L4K 3N3

11 Fairlea Avenue - Committee of Adjustment Presentation

Table of Contents

Site Plan	2
Design Drawings	
Tree Inventory and Preservation Plan	
Arborist Report	
AIDUIST REPUIT	. I C





LOT 81	11 FAIRLEA AVE.	FILE NO. A069/24
--------	-----------------	------------------

Sheet Title:

BASEMENT PLAN

1 OF

Scale: 1/8" = 1'-0"

Project Number: 24-01

KANG LI

11 FAIRLEA AVE,

CITY OF VAUGHAN


REVISIONS
1 APR .10/24
2 APR .12/24
3 MAY 1/24
4 MAY 16/24
5 MAY 29/24
6 JUNE 21/24
7 JULY 3/24

FLOOR AREA CALCULATIONS							
I EGON ANEA GAEGGEATIONG							
ROUND FLOOR AREA	=	2870	Sq. Ft.				
ECOND FLOOR AREA	=	3385	Sq. Ft.				
OTAL FLOOR AREA	=	6255	Sq. Ft.				
ST FLOOR OPEN AREAS	=	0	Sq. Ft.				
ND FLOOR OPEN AREAS	=	0	Sq. Ft.				
DD TOTAL OPEN AREAS	=	0	Sq. Ft.				
DD FIN. BASEMENT AREAS	=	3724	Sq. Ft.				
ROSS FLOOR AREA	=	9327	Sq. Ft.				
ROUND FLOOR COVERAGE*	=	2870	Sq. Ft.				
ARAGE AREA*	=	781	Sq. Ft.				
ORTICO AREA	=	69	Sq. Ft.				
OVERED PORCH AREA*	=	280	Sq. Ft.				
OTAL COVERAGE W/ PORCH	=	4000	Sq. Ft.				
	=	371.61	Sq. m.				
OTAL COVERAGE W/O PORCH	=	3651	Sq. Ft.				
	=	339.19	Sq. m.				
UILDING AREA (*)	=	3931	Sq. Ft.				
	=	365.20	Sq. m.				

K 3N3 ROBERTSONDESIGN.CA
RMEDE ROAD, UNIT 101, VAUGHAN, ONTARIO, L4K 3N3 (416) 663-0111; FAX: 1 (866) 602-1163; WWW.IANROBERTSONDESIGN.CA
RMEDE ROAD, UNIT 11 (416) 663-0111; FAX: '

ERTS

NROB



LOT 81	11 FAIRLEA AVE.	FILE NO. A069/24
--------	-----------------	------------------

Sheet Title:
GROUND FLOOR PLAN

MG

24-01

KANG LI

**** 11 FAIRLEA AVE,

CITY OF VAUGHAN

ISSUED FOR REVIEW
ISSUED FOR MINOR VARIANCE
REISSUED FOR MINOR VARIANCE

REVISIONS
1 APR .10/24
2 APR .12/24
3 MAY 1/24
4 MAY 16/24
5 MAY 29/24
6 JUNE 21/24
7 JULY 3/24

о О Н


1'-0"

Scale: 1/8"

FLOOR AREA CALCULATIONS							
ROUND FLOOR AREA	=	2870	Sq. Ft.				
ECOND FLOOR AREA	=	3385	Sq. Ft.				
OTAL FLOOR AREA	=	6255	Sq. Ft.				
ST FLOOR OPEN AREAS	=	0	Sq. Ft.				
ID FLOOR OPEN AREAS	=	0	Sq. Ft.				
DD TOTAL OPEN AREAS	=	0	Sq. Ft.				
DD FIN. BASEMENT AREAS	=	3724	Sq. Ft.				
ROSS FLOOR AREA	=	9327	Sq. Ft.				
ROUND FLOOR COVERAGE*	=	2870	Sq. Ft.				
ARAGE AREA*	=	781	Sq. Ft.				
ORTICO AREA	=	69	Sq. Ft.				
OVERED PORCH AREA*	=	280	Sq. Ft.				
OTAL COVERAGE W/ PORCH	=	4000	Sq. Ft.				
	=	371.61	Sq. m.				
OTAL COVERAGE W/O PORCH	=	3651	Sq. Ft.				
	=	339.19	Sq. m.				
JILDING AREA (*)	=	3931	Sq. Ft.				
	=	365.20	Sq. m.				

Z	
0	
S	
Œ	
Ш	
M	
0	
Z	
4	
—	
SN.CA	

20 RIVERMEDE ROAD, UNIT 101 VAUGHAN, ONTARIO, L4K 3N3 PHONE: (416) 663-0111; FAX: 1 (866) 602-1163; WWW.JANROBERT



LOT	11 FAIRLEA AVE	FILE NO. A069/24
-----	----------------	------------------

Sheet Title:
SECOND FLOOR PLAN
Project
Number: 24-01
By: MG

KANG LI
et: 11 FAIRLEA AVE,
CITY OF VAUGHAN

ISSUED FOR REVIEW
ISSUED FOR MINOR VARIANCE
REISSUED FOR MINOR VARIANCE

REVISIONS
1 APR .12/24
2 APR .12/24
3 MAY 16/24
4 MAY 16/24
5 MAY 29/24
6 JUNE 21/24
7 JULY 3/24

9


ing No.: 3 OF

Scale: 1/8" = 1'-0"

FLOOR AREA CALCULATIONS						
ROUND FLOOR AREA	=	2870	Sq. Ft.			
ECOND FLOOR AREA	=	3385	Sq. Ft.			
OTAL FLOOR AREA	=	6255	Sq. Ft.			
ST FLOOR OPEN AREAS	=	0	Sq. Ft.			
ID FLOOR OPEN AREAS	=	0	Sq. Ft.			
DD TOTAL OPEN AREAS	=	0	Sq. Ft.			
DD FIN. BASEMENT AREAS	=	3724	Sq. Ft.			
ROSS FLOOR AREA	=	9327	Sq. Ft.			
ROUND FLOOR COVERAGE*	=	2870	Sq. Ft.			
ARAGE AREA*	=	781	Sq. Ft.			
ORTICO AREA	=	69	Sq. Ft.			
OVERED PORCH AREA*	=	280	Sq. Ft.			
OTAL COVERAGE W/ PORCH	=	4000	Sq. Ft.			
	=	371.61	Sq. m.			
OTAL COVERAGE W/O PORCH	=	3651	Sq. Ft.			
	=	339.19	Sq. m.			
JILDING AREA (*)	=	3931	Sq. Ft.			
	=	365.20	Sq. m.			

IANROBERT	
20 RIVERMEDE ROAD, UNIT 101, VAUGHAN, ONTARIO, L4K 3N3 PHONE: (416) 663-0111; FAX: 1 (866) 602-1163; WWW.IANROBERTSONDESIGN.CA	





REVISIONS

| APR. 10/24 | ISSUED FOR REVIEW | 2 APR. 10/24 | ISSUED FOR MINOR VARIANCE | 3 MAY 1/24 | REISSUED FOR MINOR VARIANCE | 4 MAY 16/24 | REISSUED FOR MINOR VARIANCE | 5 MAY 29/24 | REISSUED FOR MINOR VARIANCE | 6 JUNE 21/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUED FOR MINOR VARIANCE | 7 JULY 3/24 | REISSUE

9

4 OF

Scale: 1/8" = 1'-0"

24-01

ROOF PLAN

LOT 81 11 FAIRLEA AVE. FILE NO. A069/24 | ANROBERTSON

[4.5 #1. b.]

20% of the lot area. [7.2.2 Table 7 – 3]

2 The required minimum exterior side yard shall be 9.0

3 The permitted maximum lot coverage shall not exceed

4 In R1E Zones the maximum cumulative width of both

accesses to a circular driveway, as measured at the

[14.403 #2. b. & 7.2.2 Table 7 – 3]

To permit a minimum exterior side yard of 5.36 metres.

To permit a maximum lot

coverage of 25.18%.

To permit a maximum

cumulative width of both





IANROBERTSON

ELEVATION

sct
Der: 24-01

Title: PRONT & REAR

ELEVATION

Drawn

By: MG

ng No.: 5 OF

1'-0"

Scale: 1/8"

11 FAIRLEA AVE, CITY OF VAUGHAN

ISSUED FOR REVIEW
ISSUED FOR MINOR VARIANCE
REISSUED FOR MINOR VARIANCE


REVISIONS
1 APR .10/24
2 APR .12/24
3 MAY 16/24
4 MAY 16/24
5 MAY 29/24
6 JUNE 21/24
7 JULY 3/24


r 81 EA AVE. . A069/24

LOT 11 FAIRLE FILE NO.

KANG LI

20 RIVERMEDE ROAD, UNIT 101, VAUGHAN, ONTARIO, L4K 3N3 PHONE: (416) 663-0111; FAX: 1 (866) 602-1163; WWW.IANROBERTSONDESIGN







Paul Li

April 16, 2024 Revised June 18, 2024 for TPP

Planning & Regulatory Services

Attn: Parks & Natural Heritage Planning #225 East Beaver Creek Rd, 8th Floor Richmond Hill, ON, L4C 3P4 T (905) 771-8800

Ian Roberson Design

c/o: Michael Fraser
20 Rivermede Road, Unit 101
Concord, ON L4K 3N3
T 905 669 2111
E m.fraser@ianrobertsondesign.ca

Re: 11 Fairlea Avenue (Richmond Hill)

Arborist Report

Central Tree Care Ltd. has been retained by Ian Roberson Design to provide a professional arborist report for the proposed work at 11 Fairlea Avenue.

The nature of the work includes the demolition of all structures on site to facilitate the construction of a new dwelling, garage and driveway.

To facilitate the construction permit(s) are requested for the following protected tree(s):

	Privately-Owned	Privately-Owned Neighbouring / Boundary Trees	City-Owned Trees
Injury	-	-	-
Removal	-	-	1 Hedge
Exemption	-	-	-

If there are any questions, please contact me at paul@centraltreecare.com

Thank you,

Paul Li ON-2968A Central Tree Care Ltd.

Limitations

Inspection of the trees on site was limited to a visual assessment from the ground only, unless stated otherwise. No inspection via climbing, exploration below grade, probing, or coring were conducted. Any observations and data collected from site are based on conditions at the time of inspection. Diameters of trees located on neighboring properties were estimated to avoid trespassing.

This report was completed using the following documents:

- Site plan package prepared by Ian Roberson Design., dated March 4, 2024.
- Survey prepared by Pearson and Pearson Surveying LTD.., dated February 14, 2024.

If there are any changes to the noted site plan, the consulting arborist must be notified immediately. It is the assumption that no further work, other than what has been presented in the attached site plan, has been proposed.

Tree Inventory

Table 1. The visual inspection from the ground only was completed on March 15, 2022. The location of trees marked with asterisk was approximated on the TPP; if there are any disputes regarding the location of the tree then an official survey should be conducted.

#	Species	Latin Name	DВН (cm)	TPZ (m)	Health	Structure	Assessment	Comment	Category
1	Norway maple	Acer platanoides	54	3.6	Fair- good	Fair	Codominant 4m. History of pruning. Not sealed. Surface girdle root present. Mechanical damage at base. Deadwood and hanger in canopy	Fully protect	1
2	Juniper	Juniperus sp.	~10	-	Fair- good	Fair- good	Minor needle browning	Undersized	-
3	White spruce	Picea glauca	~30	2.4	Fair- good	Fair- good	History of pruning. Stubs present. Minor deadwood	Fully protected	2
4	White spruce	Picea glauca	~41	3.0	Fair- good	Fair- good	Minor deadwood	Fully protected	2
5	Walnut	Juglans sp.	~41	3.0	Fair	Fair- good	Codominant 6m above grade. Epicormic growth. Sparse canopy	Fully protected	2
6	Walnut	Juglans sp.	~41	3.0	Fair- good	Fair- good	Codominant 6m above grade. Epicormic growth	Fully protected	2
7	Freeman maple	Acer freemanii	~20	2.4	Fair- good	Fair- good	History of pruning. Growing within hedge	Fully protected	2
H1	Cedar	Thuja occidentalis	~5-11	2.4	Good	Good	Hedge. Requiring partial removal	Permit to remove	5
H2	Cedar	Thuja occidentalis	~5-11	2.4	Good	Good	Healthy	Fully protected	5

#	Species	Latin Name	ОВН (ст)	TPZ (m)	Health	Structure	Assessment	Comment	Category
Н3	Cedar	Thuja occidentalis	~5-11	2.4	Good	Good	Healthy	Fully protected	5

- Category #: 1. Trees with diameters of 20cm or more, situated on private property on the subject site.
 - 2. Trees with diameters of 20cm or more, situated on private property, within 6m of subject site.
 - 3. Trees of all diameters situated on City owned parkland within 6m of subject site.
 - 4. Trees of all diameters situated within lands designated as a ravine or naturalized area
 - 5. Trees of all diameters situated within the City road allowance adjacent to the subject site.

Discussion

Please refer to "Recommendations" section for details on tree preservation and tree protection zone (TPZ) hoarding.

Proposed two-storey dwelling

The existing one-storey dwelling is proposed to be demolished on site. A new two-storey dwelling with garage is proposed to be constructed. The garage will be constructed within the west side yard where the existing play area will be required to be demolished to facilitate the proposed construction. The construction of the proposed dwelling and overdig will not encroach any tree or tree's TPZs. Thus, no permit is required for this proposed work.

Proposed retaining wall

A new set of retaining wall is proposed to be constructed at the south property boundary. The retaining wall is proposed to be constructed approximately 3.2m away from neighbour-owned Tree 6 with its associated overdig and will require an excavation of minimum 1.2m below grade. At this distance and excavation, the proposed work is outside the tree protection zone and no permit is required for this proposed work.

Proposed driveway

To accommodate the newly proposed garage within the southwest corner of the property, a new driveway is proposed to be constructed leading towards Fairlea Avenue. City-owned Hedge 1 is located within the footprint of the existing driveway and approximately 13.3m of the hedge will be required to be removed to facilitate the proposed driveway.

Thus, Hedge 1 will require a permit to be removed.

Fully protected trees

The proposed work will not encroach into the TPZ of the remaining by-law protected trees on or within 6.0m of the subject property, which will be fully protected. Hoarding shall be installed as per the provided TPP prior to the start of construction and shall remain standing during the construction process. After construction is complete, written permission from Urban Forestry must be granted before tree protection hoarding can be modified or removed.

Tree Replacement

As required by the Town of Richmond Hill, the tree replacement ratios are as follows:

DBH of Tree to be Removed	# of Replacement Trees Required		
0-19cm	0		
20-30cm	1		
31-40cm	2		
41-50cm	3		
51-100cm	4		
>100cm	5		

Replacement trees should be a minimum size of 60mm stem caliper at the time of planting and should be similar in size and stature to the trees being removed.

Trees being removed due to construction:


Tree #	Quantity	Category	Replacement ratio	Replacement Trees Required
Hedge 1	13.3m	0-19cm DBH Removal	0:1	0
	0			

For the removal of 13.3m of a hedge protected under by the City of Richmond Hill, no replacement trees are anticipated to be planted as compensation.

Recommendations

Recommendations for tree protection installation:

Hoarding must be installed by a qualified contractor and put in place as accurately as possible using the scale plan as the reference. It must confirm to the recommendations put forth by the Town of Richmond Hill and recommendations within this report. All the protective fencing must be maintained throughout



The construction project and its removal must be approved by the Forestry planner. All hoarding must be installed before demolition or construction commences and approved by the forestry planner.

The TPZ is established on construction sites to help protect the trees from

- Alteration of existing grades
- Changes in grade by excavating and scraping
- Movement of construction vehicles and people
- Disposal of foreign materials
- Storage of waste of construction materials

The tree protection barriers can be constructed from:

- 4ft. high plywood hoarding that can be lowered around limbs, with the supports on the outside
- 4ft. high orange plastic snow fence on a 2"X 4" frame work, this is recommended were visibility is an issue This is recommended for city trees
- If fill or excavates are going to be placed near the plastic fence a plywood barrier must be used to stop these materials from entering the TPZ.
- For minimizing compaction within the TPZ, horizontal plywood hoarding may be used.
 Horizontal hoarding consists of landscape fabric applied to grade, 30cm layer of mulch, and two
 layers of plywood secured together above the mulch. Alternatively, steel plates may be installed
 instead.
- For more information on the construction of a tree protection zone please see the City of Toronto's forestry's web site and go to By-laws and Policies.

Tree protection signage:

- This sign will be mounted on each TPZ and should be a minimum of 40cm x 60cm and made on white gator board.
- The sign must say in bold letters as a heading: Tree Protection Zone (TPZ) the rest of the text is as follows: No grade changes, storage of materials or equipment is permitted within this TPZ.
 Tree protection barriers must not be removed without written authorization of the Town of Richmond Hill, Urban Forestry Services. For info call Urban Forestry Services at (905) 771-8800, or the project consultant

Implementation of protection:

- All TPZ must be erected before any type of construction commences on the subject site.
- Before construction begins the TPZ must be inspected by city forestry staff and the consulting arborist.
- Before any digging commences around a tree subject to injury by permit, the consulting arborist must be informed.
- To dig near a tree subject to injury by permit the consulting arborist must be on site to supervise the excavation.
- Hoarding cannot be removed until all construction is finished

Photographic Documentation (May 5, 2022):



Figure 1. Front yard of the subject property on Fairlea Avenue (facing northeast).



Figure 2. Front yard of the subject property on Thornhill Avenue (facing south).



Figure 3. Tree 3 and 4 (facing southeast)





Figure 5. Tree 6 (facing south).



Figure 6. Side yard to be demolished for new garage extension (facing west).



Figure 7. City-owned Hedge 1 requiring permit to remove (facing west).



Figure 8. Tree 7 (facing northeast)